

# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

## Labour

Vehicle No. : **S3760CD** Case Owner : **0**  
 Make & Model : **ONDA ODYSSEY 2.4 EXV-S** Year of Manufacture : **2015**

S/No	Labour Description	Estimated Price	Adjusted Price	
1	To remove/refit boot compartment trims and garnish to facilitate repairs.	\$280.00	\$ 180.00	✓
2	To remove/replace rear windscreen to facilitate repairs.	\$120.00	\$ 120.00	✓
3	To transfer tailgate parts and fittings to new tailgate.	\$180.00	\$ 80.00	✓
4	Labour charges to repair and panel beat the LH rear fender, RH rear fender, rear floor panel, cutting/welding and replacing damaged parts.	\$1,440.00	\$ 720.00	✓
5	To check wiring functions.	\$40.00	\$ 20.00	✓
6	To remove/replace reverse sensor set.	\$120.00	\$ 80.00	✓
7	To putty, apply primer & spray-paint the rear bumper, tailgate, LH rear fender, RH rear fender, rear end panel, rear floor panel and affected areas.	\$1,500.00	\$ 1,000.00	✓
8	To apply rust-proofing on repaired/replaced panels.	\$150.00	\$ 50.00	✓
	Supplementary			
1	To remove/replace BlackVue camera set.	\$120.00	\$ 120.00	✓

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.