

FIRST CAPITAL

Vehicle number	SMG1767Z
Make / Model	TOYOTA NOAH
Chassis number	ZWR800343203
Accident date	10/8/20
Reference	2008-09

Qty Particulars Unit Price - SGD \$

<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER <i>torn</i>	744.00 ✓
2	FRONT RETAINER <i>Svc</i>	230.40 X
1	FRONT REINFORCEMENT <i>bst</i>	361.20 ✓
1	FRONT BUMPER SPONGE <i>torn</i>	136.60 ✓
1	FRONT BUMPER LH SIDE COVER <i>monetary broken</i>	192.50 ✓
1	FRONT BUMPER LOWER GRILLE <i>Hu</i>	204.12 X
1	FRONT LH HEADLAMP <i>monetary broken</i>	3858.25 ✓
1	FRONT GRILLE <i>Cut / monetary broken</i>	1485.54 ✓
1	FRONT BUMPER CENTER GARNISH <i>Hu</i>	1191.63 X
1	FRONT GRILLE EMBLEM <i>Hec</i>	262.20 X ✓
1	FRONT LH FENDER <i>Dented</i>	1209.80 ✓
1	FRONT LH FENDER INNER SHIELD <i>Hu</i>	339.25 X
1	FRONT LH FENDER EMBLEM <i>Hec</i>	97.75 ✓
1	BONNET <i>bst</i>	985.55 ✓
2	BONNET HINGE <i>H/S st O/S Hu</i>	179.40 ✓
1	SUPPORT PANEL <i>ren</i>	1995.25 X
1	SUPPORT PANEL TOP GARNISH <i>Hu</i>	289.30 X
1	AIRCON CONDENSER <i>Hu</i>	1691.65 X
1	RADIATOR <i>Hu</i>	2630.05 X
1	RADIATOR SIDE GARNISH <i>dented</i>	98.10 ✓
1	WIPER SIDE GARNISH <i>monetary broken</i>	79.20 ✓
		17961.74
Less 25%		4490.43
		13471.31
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
Balance B/F		13471.31
1	FRONT BUMPER CLIP <i>Hec</i>	40.00 30p
1	FRONT GRILLE CLIP <i>Hec</i>	40.00 20p
1 BOT	COOLANT <i>Hu</i>	120.00 X
1	FRONT SUPPORT PANEL TOP GARNISH CLIP <i>Hu</i>	40.00 X
1	FRONT FENDER INNER SHIELD <i>Hu</i>	40.00 X
Subtotal		280.00
Balance C/F		13751.31

3001.75

798.30

72.70

978.60

89.70

7635.95

5726.96

50.00

S/No	LABOUR AND MISCELLANEOUS CHARGES	
	Balance B/F	13751.31
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	70.00 30/-
2	REMOVE, REFIT FRONT LINING, TRIM AND GANRISH	200.00 120/-
3	REMOVE, RENEW CONDENSER AND TOP UP GAS	150.00 44
4	REMOVE, RENEW RADIATOR AND TOP UP COOLANT	150.00 44
5	TRANSFER PARTS, ATTACHMENT FROM OLD BONNET TO NEW	200.00 44
6	PANEL BEATING ON AFFECTED AREAS	1400.00 800/-
7	SPRAY PAINTING ON AFFECTED AREAS	1200.00 800/-
8	APPLY ANTI RUST ON AFFECTED AREAS	150.00 40/-
	Subtotal	3520.00
	Grand total	17271.31

7566.96

L/S 6000/-

13/08/2020 @ 1030hrs


Not Antenna

L/Sure 5 days.

Mya

LKK Auto

Check part prices.



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____