

FIRST CAPITAL

|                |              |
|----------------|--------------|
| Vehicle number | SMG1767Z     |
| Make / Model   | TOYOTA NOAH  |
| Chassis number | ZWR800343203 |
| Accident date  | 10/8/20      |
| Reference      | 2008-09      |

Qty Particulars Unit Price - SGD \$

| <u>PARTS REPLACEMENT - LIST ITEMS</u>         |                                                   |            |
|-----------------------------------------------|---------------------------------------------------|------------|
| 1                                             | FRONT BUMPER <i>turn</i>                          | 744.00 ✓   |
| 2                                             | FRONT RETAINER <i>Svc</i>                         | 230.40 X   |
| 1                                             | FRONT REINFORCEMENT <i>wt</i>                     | 361.20 ✓   |
| 1                                             | FRONT BUMPER SPONGE <i>turn</i>                   | 136.60 ✓   |
| 1                                             | FRONT BUMPER LH SIDE COVER <i>mounting broken</i> | 192.50 ✓   |
| 1                                             | FRONT BUMPER LOWER GRILLE <i>HN</i>               | 204.12 X   |
| 1                                             | FRONT LH HEADLAMP <i>mounting broken</i>          | 3858.25 ✓  |
| 1                                             | FRONT GRILLE <i>cut 1 mounting broken</i>         | 1185.54 ✓  |
| 1                                             | FRONT BUMPER CENTER GARNISH <i>HN</i>             | 1191.63 X  |
| 1                                             | FRONT GRILLE EMBLEM <i>HN</i>                     | 262.20 X ✓ |
| 1                                             | FRONT LH FENDER <i>Dented</i>                     | 1209.80 ✓  |
| 1                                             | FRONT LH FENDER INNER SHIELD <i>HN</i>            | 339.25 X   |
| 1                                             | FRONT LH FENDER EMBLEM <i>HN</i>                  | 97.75 ✓    |
| 1                                             | BONNET <i>wt</i>                                  | 985.55 ✓   |
| 2                                             | BONNET HINGE <i>W/S 5t O/S HN</i>                 | 179.40 ✓   |
| 1                                             | SUPPORT PANEL <i>new</i>                          | 1995.25 X  |
| 1                                             | SUPPORT PANEL TOP GARNISH <i>HN</i>               | 289.30 X   |
| 1                                             | AIRCON CONDENSER <i>HN</i>                        | 1691.65 X  |
| 1                                             | RADIATOR <i>HN</i>                                | 2630.05 X  |
| 1                                             | RADIATOR SIDE GARNISH <i>dented</i>               | 98.10 ✓    |
| 1                                             | WIPER SIDE GARNISH <i>mounting broken</i>         | 79.20 ✓    |
|                                               |                                                   | 17961.74   |
| Less 25%                                      |                                                   | 4490.43    |
|                                               |                                                   | 13471.31   |
| <u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u> |                                                   |            |
| Balance B/F                                   |                                                   | 13471.31   |
| 1                                             | FRONT BUMPER CLIP <i>HN</i>                       | 40.00 30p  |
| 1                                             | FRONT GRILLE CLIP <i>HN</i>                       | 40.00 20p  |
| 1 BOT                                         | COOLANT <i>HN</i>                                 | 120.00 X   |
| 1                                             | FRONT SUPPORT PANEL TOP GARNISH CLIP <i>HN</i>    | 40.00 X    |
| 1                                             | FRONT FENDER INNER SHIELD <i>HN</i>               | 40.00 X    |
| Subtotal                                      |                                                   | 280.00     |
| Balance C/F                                   |                                                   | 13751.31   |

| S/No | <u>LABOUR AND MISCELLANEOUS CHARGES</u>           |                          |
|------|---------------------------------------------------|--------------------------|
|      | Balance B/F                                       | 13751.31                 |
| 1    | CHECK FRONT WIRING AND LIGHTNING SYSTEM           | <del>20.00</del> 30/-    |
| 2    | REMOVE, REFIT FRONT LINING, TRIM AND GANRISH      | <del>200.00</del> 120/-  |
| 3    | REMOVE, RENEW CONDENSER AND TOP UP GAS            | 150.00 44                |
| 4    | REMOVE, RENEW RADIATOR AND TOP UP COOLANT         | 150.00 44                |
| 5    | TRANSFER PARTS, ATTACHMENT FROM OLD BONNET TO NEW | 200.00 44                |
| 6    | PANEL BEATING ON AFFECTED AREAS                   | <del>1400.00</del> 800/- |
| 7    | SPRAY PAINTING ON AFFECTED AREAS                  | <del>1200.00</del> 800/- |
| 8    | APPLY ANTI RUST ON AFFECTED AREAS                 | <del>150.00</del> 40/-   |
|      | Subtotal                                          | 3520.00                  |
|      | Grand total                                       | 17271.31                 |

13/08/2020 @ 1030hrs

Not Antm

L/Sune 5 days.

Ryan

LKK Auto

Check part prices.



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: