

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
 Sin Ming AutoCity, Singapore 575722
 Tel: 6452 7018 Fax: 6458 3895
 Email: service@kkimhin.com.sg

No. : 31295

Vehicle Insured : SHC 3157 B
 Accident Date : 05-Aug-2020

Date : 07-Aug-2020

Our Ref : 020333 (FIRST CAP) / QUEK

PAGE : 1

MICHAEL TEE ENG HUI (MR)
 Singapore

Not Authorized
L/Bump & Resurvey After Paint
7 days

ESTIMATED COST OF REPAIR FOR TOYOTA COROLLA ALTIS 1.6A (2009) SJS3172Z
 =====

| | | | |
|--|-------------|-----------------------|---|
| 1 pc front bumper | | <i>BT/CM</i> 581.70 | ✓ |
| 1 pc front bumper centre lower grille | | <i>DIY</i> 129.20 | ✓ |
| 2 pcs front bumper side retainer (LH/RH) | @ S\$ 63.40 | <i>N/S DIY</i> 126.80 | ✓ |
| 10 pcs front bumper clips | @ S\$ 5.50 | <i>M</i> 55.00 | ✓ |
| 1 pc n/s front bumper fog cover | | <i>M</i> 65.30 | ✓ |
| 1 pc n/s front bumper fog lamp | | <i>M</i> 301.90 | ? |
| 1 pc front bumper reinforcement | | <i>M</i> 343.70 | ✓ |
| 2 pcs front bumper reinforcement bracket (LH/RH) | @ S\$ 55.70 | 111.40 | ? |
| 1 pc front bumper logo | | <i>M</i> 74.10 | ✓ |
| 1 pc front bumper top seal | | <i>M</i> 54.80 | ✓ |
| 1 pc front grille assy | | 397.50 | ? |
| 2 pcs headlamp assy (LH/RH) <i>N/S Br</i> | @ S\$713.80 | 1,427.60 | ✓ |
| 1 pc n/s front fender | | <i>M</i> 712.10 | ✓ |
| 1 pc n/s front fender inner panel | | <i>N/S M</i> 569.10 | ? |
| 2 pcs n/s front fender 'VVTI' emblem | @ S\$ 50.80 | <i>M</i> 101.60 | ✓ |
| 1 pc n/s front fender inner shield | | <i>DIY</i> 196.50 | ✓ |
| 8 pcs n/s front fender inner shield clips | @ S\$ 5.50 | <i>M</i> 44.00 | ✓ |
| 1 pc n/s front fender inner shield retainer clip | | <i>M</i> 29.70 | ✓ |
| 1 pc front support panel | | <i>M</i> 821.10 | ✓ |
| 1 pc battery top bracket | | <i>M</i> 40.00 | ✓ |
| 1 pc battery base tray | | <i>M</i> 60.80 | ? |
| 1 pc air intake duct | | <i>M</i> 54.00 | ✓ |
| 1 pc air intake inner hose | | 130.70 | ? |
| 1 pc air resonator | | <i>M</i> 187.60 | ✓ |
| 1 pc air cleaner box | | <i>CM</i> 1,140.10 | ✓ |

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SHC 3157 B
Our Ref : 020333

Page : 2
No. : 31295

| | | | |
|--|-------------------------|-----------|------|
| | | 98.20 | ? |
| 1 pc fuses & relays box - top | | 103.70 | ? |
| 1 pc fuses & relays box - lower | | 209.40 | ? |
| 1 pc fuses & relays box - centre | | 1,041.60 | ✓ |
| 1 pc bonnet | | 98.70 | ✓ |
| 1 pc bonnet lock | | 120.00 | ✓ |
| 2 pcs bonnet hinges (LH/RH) | @ S\$ 60.00 | 62.80 | ✓ |
| 1 pc bonnet outer seal | | 280.80 | ✓ |
| 1 pc bonnet insulation | | 38.50 | ✓ |
| 7 pcs bonnet insulation clips | @ S\$ 5.50 | 145.80 | X |
| 1 pc n/s bonnet nozzle jet (for windscreen) | | | |
| 2 pcs front wiper panel garnish (LH/RH) | <i>misc</i> @ S\$528.50 | 1,057.00 | ✓ |
| 1 pc air con condenser | | 1,801.70 | ? |
| 1 pc radiator | | 2,390.70 | ? |
| 1 pc radiator top garnish | | 101.00 | ? |
| 1 pc radiator fan cowling | | 297.20 | ? |
| 1 pc radiator fan blade | | 179.70 | X |
| 1 pc radiator fan motor | | 296.50 | X |
| 1 pc engine lower cross member | | 1,943.20 | ? |
| 1 pc front engine undercover | | 156.50 | X |
| 1 pc engine mounting - LH | | 215.00 | ? |
| 1 pc engine mounting bracket - LH | | 104.00 | ? |
| 1 pc engine mounting - RH | | 437.40 | X |
| 1 pc engine mounting bracket - RH | | 149.00 | X |
| 1 pc engine mounting - front | | 241.90 | ? |
| 1 pc engine mounting bracket - front | | 211.00 | ? |
| 1 pc engine mounting - rear | | 291.00 | ? |
| 1 pc engine mounting bracket - rear | | 215.00 | X |
| | | 20,043.60 | |
| | Less 25% : | -5,010.90 | |
| | | 15,032.70 | |
| | | 40.00 | sn ✓ |
| 1 pc front number plate | | 180.00 | sn ? |
| 1 pc battery | | | |

Con't Page 3 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
 Sin Ming AutoCity, Singapore 575722
 Tel: 6452 7018 Fax: 6458 3895
 Email: service@kkimhin.com.sg

Vehicle Insured : SHC 3157 B
 Our Ref : 020333

Page : 3
 No. : 31295

| | | |
|---|---------------------|------------------------------|
| 1 pc radiator coolant | | <i>sn</i> 48.00 <i>sn</i> |
| 1 pc radio headset | | <i>sn</i> 450.00 <i>sn</i> X |
| To tow accident vehicle to workshop by normal towing | 60.00 | <i>50/</i> |
| To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts. | 1,200.00 | <i>900/</i> |
| To focus headlamps. To check front wiring and lighting operation. | 50.00 | <i>20/</i> |
| To remove aircon condenser, pipes and driers. Vaccum and recharge gas | 100.00 | <i>✓</i> |
| To putty and respray on affected portions. | 1,400.00 | <i>1200/</i> |
| To conduct front wheel alignment test. | <i>sn</i> 80.00 | <i>X</i> |
| To check and realignment on chassis member. | 300.00 | <i>7</i> |
| To remove and refit engine assy in order to facilitate repairing works | 280.00 | <i>?</i> |
| Total : | S\$19,220.70 | ===== |

Singapore Dollars Nineteen Thousand Two Hundred
 and Twenty and Cents Seventy Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: