



## 金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkinhin.com.sg

No. : 31295

Vehicle Insured : SHC 3157 B  
Accident Date : 05-Aug-2020

Date : 07-Aug-2020

Our Ref : 020333 (FIRST CAP) / QUEK

PAGE : 1

MICHAEL TEE ENG HUI (MR)  
Singapore

*Not Authorized  
L1 Samp @ 8950/5  
Resurvey After Paint  
9 days*

ESTIMATED COST OF REPAIR FOR TOYOTA COROLLA ALTIS 1.6A (2009) SJS3172Z  
=====

1 pc front bumper	456.30	BT1 CMA	581.70	✓
1 pc front bumper centre lower grille		DIY	129.20	✓
2 pcs front bumper side retainer (LH/RH)		NLS DIY	126.80	✓
10 pcs front bumper clips		@ S\$ 5.50	55.00	✓
1 pc n/s front bumper fog cover		DIY	65.30	✓
1 pc n/s front bumper fog lamp		Mfg Bro	301.90	✓
1 pc front bumper reinforcement		BT	343.70	✓
2 pcs front bumper reinforcement bracket (LH/RH)		@ S\$ 55.70	111.40	✓
1 pc front bumper logo		DIY	74.10	✓
1 pc front bumper top seal		DIY	54.80	✓
1 pc front grille assy	311.20	CMA	397.50	✓
2 pcs headlamp assy (LH/RH)	NLS Bro	@ S\$ 713.80	1,427.60	✓ + d/su
1 pc n/s front fender	581.90	BT	712.10	✓
1 pc n/s front fender inner panel		NLS	569.10	✓
2 pcs n/s front fender 'VVTI' emblem		@ S\$ 50.80	101.60	✓
1 pc n/s front fender inner shield		DIY	196.50	✓
8 pcs n/s front fender inner shield clips		@ S\$ 5.50	44.00	✓
1 pc n/s front fender inner shield retainer clip		DIY	29.70	✓
1 pc front support panel	708.40	BT	821.10	✓
1 pc battery top bracket		BT	40.00	✓
1 pc battery base tray		DIY	60.80	✓
1 pc air intake duct		DIY	54.00	✓
1 pc air intake inner hose		DIY	130.70	✓
1 pc air resonator		DIY	187.60	✓
1 pc air cleaner box	857.00	CMA	1,140.10	✓

## 金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkimhin.com.sg

Vehicle Insured : SHC 3157 B  
Our Ref : 020333

Page : 2  
No. : 31295

1 pc fuses & relays box - top		Sn 98.20		X
1 pc fuses & relays box - lower		Sn 103.70		X
1 pc fuses & relays box - centre		Sn 209.40		X
1 pc bonnet <span style="float: right;">894.50</span>		Bn 1,041.60		X
1 pc bonnet lock		DIT 98.70		—
2 pcs bonnet hinges (LH/RH) @ S\$ 60.00		Bn 120.00		—
1 pc bonnet outer seal		Cm 62.80		—
1 pc bonnet insulation		Cm 280.80		—
7 pcs bonnet insulation clips @ S\$ 5.50		Mn 38.50		—
1 pc n/s bonnet nozzle jet (for windscreen)		Sn 145.80		X
2 pcs front wiper panel garnish (LH/RH) @ 366.10	M/Cm	@ S\$528.50 1,057.00		L
1 pc air con condenser <span style="float: right;">1217.85</span>		TT/Pu 1,801.70		X
1 pc radiator <span style="float: right;">2030</span>		" 2,390.70		X
1 pc radiator top garnish		Cm 101.00		X
1 pc radiator fan cowling		Cm 297.20		X
1 pc radiator fan blade		Mn 179.70		X
1 pc radiator fan motor		Sn 296.50		X
1 pc engine lower cross member		Sn 1,943.20		X
1 pc front engine undercover		Sn 156.50		X
1 pc engine mounting - LH		Sn 215.00		X
1 pc engine mounting bracket - LH		Sn 104.00		X
1 pc engine mounting - RH		Sn 437.40		X
1 pc engine mounting bracket - RH		Sn 149.00		X
1 pc engine mounting - front		Sn 241.90		X
1 pc engine mounting bracket - front		R 211.00		X
1 pc engine mounting - rear		Sn 291.00		X
1 pc engine mounting bracket - rear		Sn 215.00		X
		-----		
		20,043.60		
	Less 25% :	-5,010.90		
		-----		
		15,032.70		
1 pc front number plate		Bn 40.00 sn		X
1 pc battery		Cm / Rcl 180.00 sn		X

**金興(龔)汽車私人有限公司**

160 Sin Ming Drive, #02-20,  
 Sin Ming AutoCity, Singapore 575722  
 Tel: 6452 7018 Fax: 6458 3895  
 Email: service@kkinhin.com.sg

Vehicle Insured : SHC 3157 B  
 Our Ref : 020333

Page : 3  
 No. : 31295

1 pc radiator coolant  
 1 pc radio headset

*short* *na* 48.00 *20sn* sn  
 450.00 *50sn* sn

To tow accident vehicle to workshop  
 by normal towing

60.00 *50l*

To remove, cut out damaged parts,  
 panel beating, welding, align,  
 refix and to renew affected parts.

1,200.00 *950/-*  
~~200~~

To focus headlamps. To check front  
 wiring and lighting operation.

50.00 *20l*

To remove aircon condenser, pipes  
 and driers. Vaccum and recharge gas

100.00 ✓

To putty and respray on affected  
 portions.

1,400.00 *1200l*

To conduct front wheel alignment  
 test.

*na* 80.00 *X*

To check and realignment on chassis  
 member.

300.00 *250l*

To remove and refit engine assy  
 in order to facilitate repairing  
 works

*na* 280.00 *X*

Total : S\$19,220.70  
 =====

Singapore Dollars Nineteen Thousand Two Hundred  
 and Twenty and Cents Seventy Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: