



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 ROC number : 201015366H
 REPAIR PERFORMA INVOICE

AIG Singapore
 78 Shenton Way
 Singapore 079120

Vehicle number	YM3777H
Make / Model	MITSUBISHI / FK617MSJRDEC
Chassis number	FK617MB10198
Accident date	11 August 2020
Reference	2008-16

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR TAILLAMP LH <i>mounting broken</i>	424.18 ✓
1	REAR TAILLAMP RH <i>mounting broken</i>	424.18 ✓
1	REAR TAILLAMP PANEL LH <i>bst</i>	296.33 ✓
1	REAR TAILLAMP PANEL RH <i>bst</i>	296.33 ✓
1	REAR NUMBER PLATE LAMP <i>svc</i>	87.30 X
1	REAR NUMBER PLATE GARNISH <i>bst</i>	109.39 ✓
1	REAR STOPPER LH <i>HH</i>	89.29 X
1	REAR STOPPER RH <i>HH</i>	89.29 X
		1816.29
	Less 15 %	272.44
	Subtotal	1543.85
	Balance C/F	1543.85
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1	REAR RH WOODEN CROSS MEMBER <i>dam</i>	1500.00 X
1	REAR LOWER MEMBER -UPPER <i>(wooden)</i>	550.00 ✓
1	REAR LOWER MEMBER <i>HH</i>	1250.00 X
1	STEP PANEL <i>bst</i>	1400.00 ✓
2	STEP PANEL BRACKET <i>bst</i>	600.00 ✓
1	U-BRACKET RH <i>bst</i>	450.00 ✓
1	TAILGATE LH <i>HH</i>	1600.00 X
1	TAILGATE RH <i>HH</i>	1600.00 X
6	TAILGATE HINGE <i>HH</i>	180.00 X
1	TAILGATE RODE LH <i>HH</i>	130.00 X
1	TAILGATE RODE RH <i>HH</i>	130.00 X
1	TAILGATE LOCK FLIP LH <i>HH</i>	150.00 X
1	TAILGATE LOCK FLIP RH <i>HH</i>	150.00 X
1	60KM/H STICKER <i>HH</i>	70.00 X
1	REAR NUMBER PLATE <i>bst</i>	80.00 15/-
	Subtotal	9840.00
	Balance C/F	11383.85
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	11383.85
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 30/-
2	TRANSFER PARTS, ATTACHMENT FROM OLD LH TAILGATE TO NEW	200.00 HH
3	TRANSFER PARTS, ATTACHMENT FROM OLD RH TAILGATE TO NEW	200.00 HH
4	PANEL BEATING ON AFFECTED AREAS	1600.00 800/-
5	SPRAY PAINTING ON AFFECTED AREAS	1400.00 300/-
6	APPLY ANTI RUST ON AFFECTED AEREAS	120.00 80/-
	Subtotal	3580.00
	Grand total	14963.85

1550.41
 1317.84

3015.00

1210.00

5542.84
 4154400/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

14/08/2020 @ 1230hrs
 Not Authorised
 L/sure 6 days.
 J. Tan LKK Auto