



Case Details

Case Reference Number : TAX/08/20/2021
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHF280G

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-12268-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 11/08/2020 02:27 AM
 Vehicle Age(In Months) : 8

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			COVER, RR BUMPER ASSY	1	485.60	485.60	25.00	364.20	Replace	1	0	Repair	✓ X R
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 1	2	4.00	8.00	25.00	6.00	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 2	2	4.00	8.00	25.00	6.00	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 3	2	11.00	22.00	25.00	16.50	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.30	22.60	25.00	16.95	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	374.50	374.50	25.00	280.88	Replace	1	280.88	Replace	✓ / SCR.
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	332.70	332.70	25.00	249.52	Replace	0	0	Check	✓ X SVC
One Time Key In	Main			REVERSE SENSOR SET	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	✓ / Nec
									Total Spare Part Cost	1,240.05	Surveyor Total 400.88			
									Lump Sum Discount (%)	0.00	Lump Sum Dis (%) 0			
									Final Spare Part Cost	1,240.05	Final Sur Total 400.88			

11/08/2020

https://vacaweb.smrt.com.sg/Estimation.aspx

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	338.00	200	
Total:			338.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY REAR BUMPER REINFORCEMENT	180.00	0	
Total:			558.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
2	Main	TO REPLACE SUNDRY PARTS	100.00	0	
3	Main	TO WASH AND VACUUM	60.00	0	
Total:			280.00	0.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	1,240.05	400.88
Total Labour Cost	338.00	200.00
Total Spray Painting	558.00	200.00
Other	280.00	0.00
Overall Total	2,416.05	800.88
Lump Sum Repair Option		☐
Lump Sum Total	0.00	800.88
Surveyor Approved Amount		800.88
No of Repair Days*	3	2 2 days

11/08/2020

https://vacswed.smt.com.sg/estimation.aspx

Estimator Assessment(\$)

Surveyor Assessment(\$)

Remarks

P/P, before paint photo.

Surveyor Name

Sun Pin (LKK)

Signature



Save

Clear

Survey Date

11/08/2020

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: