

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 45257

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0564/2020/NS
Date : 13-Aug-20

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Veh No : YP 8794 J

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street
#19-00 The Octagon
Singapore 069534

Hi Rasul

5 days - ok - jb - 9 Dec 20

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name : Mr Paolo Misurale
Address : 15 Cove Drive
#04-13
Singapore 098328
Telephone : HP +65 90903160
Type of Claim : Third Party Claim
Policy No. :
Vehicle No : **SLR 8664 U**
Model Code : KIA Sportage 2.0
Model / Year : Aug-17
Engine No : G4NAHH755870
Chassis No : KNAPR81AMH7369640
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 2-Aug-20
Place of Accident : Sentosa Gateway The Exit Gantry

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLR 8664 U

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	180.00	\$ 180.00
2	To remove and renew rhs headlight.	S/N \$	250.00	\$ 250.00
3	To dismantle and renew front bumper, bonnet and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$	1,500.00	\$ 1,175.00
4	To respray front bumper and bonnet.	\$	1,500.00	\$ 900.00
5	To carry out diagnostic check.	S/N \$	100.00	\$ 100.00
TOTAL LABOUR CHARGES		:	\$ 3,530.00	\$ 2,605.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 8664 U

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 850.00	\$ 850.00
2	FRONT BUMPER EMBLEM	\$ 90.00	\$ 90.00
3	FRONT BUMPER SEAL	\$ 54.00	\$ 54.00
4	FRONT BUMPER UPPER COVER	\$ 135.00	\$ 60.00
5	RADIATOR GRILLE	\$ 570.00	\$ 570.00
6	HEADLIGHT-RH	\$ 3,250.00	\$ 3,250.00
7	BONNET	\$ 1,200.00	\$ 1,200.00
8	BONNET NOISE INSULATOR	\$ 240.00	
9	FRONT NO. PLATE BASE	\$ 16.00	
10	PACKING ADHSIVE	\$ 19.00	
11	FRONT NO. PLATE	S/N \$ 60.00	\$ 60.00
12	SUPPLEMENTARY	\$ 30.00	\$ 30.00
13	SUNDRIES	\$ 100.00	
TOTAL SPARE PARTS CHARGES		: \$ 6,614.00	\$ 6,164.00
TOTAL LABOUR CHARGES		: \$ 3,530.00	\$ 2,605.00
GRAND TOTAL		: \$ 10,144.00	\$ 8,769.00

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 1

GST Reg No. 19-9902271-W

China Taiping Insurance (SG) Pte Ltd 105 Cecil Street #19-00 The Octagon Singapore 069534 Attn: Motor Claims Dept Tel: Fax 6338 1504		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0564/2020/NS 2-Oct-20 George Wong 1 OF 1 SLR 8664 U KIA Sportage 2.0
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	FRONT BUMPER SIDE BRACKET-RH	\$ 30.00	\$ 30.00
TOTAL		\$ 30.00	\$ 30.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant