# **Premium Automobiles**

55 Ubi Road 1, Singapore 408699

Telefax

## Estimated Labour Charges for Accident Vehicle SLR 8664 U

S/r	Nature of Jobs		2000	stimated Charges	Surveyor's Recommendations
1	Taransia shock and reinstall front wire harness for	s/N	\$		//
2	To remove and renew rhs headlight.	S/N	\$	250.00	//
	To dismantle and renew front bumper, bonnet and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	4	\$		1175/
4	To respray front bumper and bonnet.		\$	1,500.00	900/
	To carry out diagnostic check.	S/N	\$	100.00	//
	TOTAL LABOUR CHARGES	:	\$	3,530.00	18 01

# **Premium Automobiles**

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefay

Material List for Accident Vehicle Regn No. SLR 8664 U

		<u>D</u>	Damaged Parts & Prices	
Parts Description			S/Nett	Remarks
FRONT BUMPER de	\$		850.00	/
	5	,	90.00	
	9	5	54.00	/
		5	135.00	60/
RADIATOR GRILLE SCA		5	570.00	/
		\$	3,250.00	
		\$	1,200.0	0/
		\$	240.0	0
FRONT NO. PLATE BASE X SVC		\$	16.0	0
PACKING ADHSIVE W XAA		\$	19.0	0
FRONT NO. PLATE 5+	S/N	\$	60.0	00/
		\$	100.0	00
	Hebott marg	\$	6,584.0	0
		\$	3,530.0	0
GRAND TOTAL	nema mat	\$	10,114.0	00
	FRONT BUMPER EMBLEM PER FRONT BUMPER SEAL PER FRONT BUMPER SEAL PER FRONT BUMPER UPPER COVER FOR PACKING ADHSIVE PACKING ADHSI	FRONT BUMPER DE FRONT BUMPER EMBLEM PAR SEAL PAR SEAL PACKING ADHSIVE PACKING	FRONT BUMPER des  FRONT BUMPER EMBLEM RES  FRONT BUMPER SEAL RES  FRONT BUMPER UPPER COVER Ades  FRONT BUMPER UPPER COVER Ades  FRONT BUMPER UPPER COVER Ades  S  RADIATOR GRILLE SUM  S  HEADLIGHT-RH  S  BONNET NOISE INSULATOR ASSULATION  FRONT NO. PLATE BASE ASSULATION  FRONT NO. PLATE BASE ASSULATION  S  SUNDRIES  TOTAL SPARE PARTS CHARGES  TOTAL LABOUR CHARGES  S  S  S  S  S  TOTAL SPARE PARTS CHARGES  S  TOTAL SPARE PARTS CHARGES	Parts Description         S/Nett           FRONT BUMPER des         \$ 850.00           FRONT BUMPER EMBLEM No.         \$ 90.00           FRONT BUMPER SEAL No.         \$ 54.00           FRONT BUMPER UPPER COVER Holes         \$ 135.00           RADIATOR GRILLE SCAL         \$ 570.00           HEADLIGHT-RH GNAL         \$ 3,250.00           BONNET LATER SCAL         \$ 1,200.00           BONNET NOISE INSULATOR HOLE         \$ 240.0           FRONT NO. PLATE BASE         \$ 16.0           PACKING ADHSIVE         \$ 19.0           FRONT NO. PLATE LATER         \$ 60.0           SUNDRIES         \$ 100.0           TOTAL SPARE PARTS CHARGES         \$ 6,584.0           TOTAL LABOUR CHARGES         \$ 3,530.0

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

### **Premium Automobiles**

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

#### Telefax

Name

Surveyed Date

**Authorised Date** 

**Excess Cost** 

Liability

Remarks

: RASUL - 14 90010068 : 17/08/2021 @ 1300 : 5 days : Rasny Lafore paint

Please Note

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo Body Repair Manager

Allan Wu Claims Consultant