



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

TRANS-CAB AUTO SERVICES PTE LTD  
NO.2 ANG MO KIO STREET 63  
SINGAPORE 569111

INV No. AC2005977  
INV Date 01/09/2020  
Reference CS/TP20008408/Ksf3e2  
Code TP378



### PROFESSIONAL SERVICE FEE

Vehicle No. SHD 9985H

Insured Veh.

Claim No.

Policy No.

Accident Date 08/08/2020

Inspection Date 13/08/2020

Description	Total
Survey Inspection	352.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>352.00</b>
<b>GST (7%)</b>	<b>24.64</b>
<b>Grand Total</b>	<b>376.64</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*KHM*




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TRANS-CAB AUTO SERVICES PTE LTD		Ref : CS/TP20008408/Ksf3e2		
NO.2 ANG MO KIO STREET 63SINGAPORE 569111		Date : 01-09-2020		
		Code : TP378		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	Veh. Inspected		SHD 9985H	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		13/08/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	JTDKB3FU603091272	Colour	M.P. WHITE / RED	
Odometer	2777	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	DUNLOP	9 mm	
L/H Front Tyre	195/60 R15	DUNLOP	9 mm	
R/H Rear Tyre	195/60 R15	DUNLOP	9 mm	
L/H Rear Tyre	195/60 R15	DUNLOP	9 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	08/08/2020	Inspection Date	13/08/2020	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>2 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9985H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	COVER, REAR BUMPER	DENTED / CRACKED	485.60	485.60
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	TO REPAIR SEE LABOUR	332.70	-
1	GUARD, REAR BUMPER, CENTER	SERVICEABLE	374.50	-
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	132.60	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	132.60	-
1	REFLECTOR ASSY, REFLEX	SERVICEABLE	39.00	-
1	REAR TAILGATE OUTER GARNISH	SERVICEABLE	913.60	-
1	REAR TAILGATE WEATHERSTRIP	SERVICEABLE	372.30	-
1	LENS & BODY, REAR COMBINATION LAMP, NO.2	SERVICEABLE	261.00	-
1	LENS & BODY, REAR COMBINATION LAMP	SERVICEABLE	339.60	-
1	LAMP ASSY, REAR	SERVICEABLE	293.60	-
	LESS 25% DISCOUNT		-919.28	-121.40
			2,757.82	364.20
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	75.00	75.00
1	REAR TAILGATE TOYOTA LOGO (SN)	NOT NECESSARY	47.90	-
1	REAR TAILGATE WORDING 'PRIUS' (SN)	NOT NECESSARY	54.60	-
1	REAR TAILGATE WORDING 'HYBRID' (SN)	NOT NECESSARY	54.60	-
1	REAR TAILGATE STICKER 'TRANS-CAB' (SN)	NOT NECESSARY	80.00	-
1	REAR TAILGATE STICKER '6555-3333' (SN)	NOT NECESSARY	80.00	-
1	REAR RH BUMPER RETAINER CLIP (SN)	NOT NECESSARY	65.00	-
1	REAR LH BUMPER RETAINER CLIP (SN)	NOT NECESSARY	65.00	-
			1,222.10	75.00
<b><u>LABOUR</u></b>				
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-

Report Ref No. CS/TP20008408/Ksf3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,600.00	220.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	50.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	170.00	-
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REINFORCEMENT SUB-ASSY, REAR BUMPER.		1,600.00	150.00
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.	NOT NECESSARY	250.00	-
			4,340.00	420.00
<b>GRAND TOTAL</b>			<b>8,319.92</b>	<b>859.20</b>

<b>RECOMMENDED COST OF REPAIRS</b>				<b>859.20</b>
------------------------------------	--	--	--	---------------

Report Ref No. CS/TP20008408/Ksf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 9985H

INSPECTION








## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 9985H

RE-INSPECTION

