

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 45347

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0569/2020/NS
Date	:	13-Aug-20

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : SGN 6116 D

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Ng Lay Khim Jane
Address	:	25 Soo Chow Way Singapore 575322
Telephone	:	(HP) +65 98365788
Type of Claim	:	Third Party Claims
Policy No.	:	MP311911
Vehicle No	:	SLW 2912 S
Model Code	:	Audi Q2 1.0 TFSI S Tronic
Model / Year	:	2/5/2018
Engine No	:	CHZ 634588
Chassis No	:	WAUZZZGA6Ja054993
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	12-Aug-20
Place of Accident	:	Newton Circus Along Scotts Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLW 2912 S

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and reinstall rear parking aid. Check function and renew according to damage.	S/N \$ 280.00 /	
2	To dismantle and renew rear bumper and rear bumper spoiler. Re-organise crash management components. Reinstall all parts removed.	\$ 1,200.00 500	
3	To respray rear bumper.	\$ 1,000.00 550	
4	To carry out diagnostic check.	S/N \$ 192.00 /	
TOTAL LABOUR CHARGES		: <u>\$ 2,672.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2912 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER <i>de</i> ✓	\$ 1,164.00	
2	REAR BUMPER FIXING PARTS <i>new</i> ✓	\$ 76.00	
3	REAR BUMPER SPOILER <i>cut</i> ✓	\$ 281.00	
4	REAR BUMPER TOWING EYE COVER X	\$ 43.00	
5	REAR LIGHT REFLECTOR - RH <i>scr</i> ✓	\$ 30.00	
6	REAR PARKING AID SENSOR - OUTER ?	TBC	
7	REAR PARKING AID SEAL RING <i>new</i> ✓	4 \$ 14.00	
8	REAR BUMPER CARRIER ? X	\$ 544.00	
9	REAR BUMPER HOLDING STRAP - LH / RH - ? X	21 \$ 26.00	
10	REAR BUMPER GUIDE SECTION - RH ?	\$ 53.00	
11	TAIL LIGHT - RH <i>scr</i> ✓	\$ 1,306.00	
12	TAIL LIGHT TRIM - RH X	\$ 30.00	
13	REAR WHEEL COVER - LH / RH <i>new</i> ✓	2 \$ 336.00	
14	SUNDRIES ?	\$ 200.00	
TOTAL SPARE PARTS CHARGES		: \$ 4,103.00	
TOTAL LABOUR CHARGES		: \$ 2,672.00	
GRAND TOTAL		: <u>\$ 6,775.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Rasmi - Hp 90010068
Surveyed Date : 19/08/2020 @ 1440
Authorised Date :
Excess Cost : 3 days
Liability :
Remarks : Resurvey before paint

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant