


PRS send on :
Date of accident : 07/08/2020
Our vehicle : GBH8242A
your vehicle : SDH1114J

Vehicle number : GBH8242A
Vehicle mark / model : TOYOTA HIACE 2.8 MANUAL
Engine number : 1KD2827560
Chassis number : JTFHT02P500245405

This vehicle GBH8242A in our workshop repair was sustain at the **REAR CENTRE PORTION SIDE** damage .



Estimate on parts

NO	QTY	PARTS DISCRIPTION	PART NO	PARTS PRICE
1	1	Tailgate assy <i>sf</i>		\$ 2,250.00
2	1	Tailgate inner trim broad ?		\$ 220.00
3	1	Tailgate HIACE emblem <i>new</i>		\$ 68.00
4	1	Tailgate toyota logo <i>new</i>		\$ 75.00
5	1	Tailgate damper LH <i>X</i>		\$ 330.00
6	1	Tailgate damper RH <i>X</i>		\$ 330.00
7	1	Tailgate lock assy ?		\$ 310.00
8	1	Tailgate lock striker <i>?</i>		\$ 130.00
9	1	Tailgate center granish <i>X</i>		\$ 297.00
10	1	Tailgate weather strip <i>new</i>		\$ 280.00
11	1	Tailgate side rubber LH <i>?</i>		\$ 50.00
12	1	Tailgate side rubber RH <i>?</i>		\$ 50.00
13	1	Rear bumper assy <i>de</i>		\$ 1,220.00
14	1	Rear bumper side retainer LH <i>X</i>		\$ 98.50
15	1	Rear bumper side retainer RH <i>X</i>		\$ 98.50
16	1	Taillamp assy LH <i>X</i>		\$ 450.00
17	1	Taillamp assy RH <i>X</i>		\$ 450.00
18	1	Outer rear end panel assy <i>sf</i>		\$ 925.00
19	1	Inner rear end panel assy <i>sf</i>		\$ 930.00
Total parts				\$ 8,562.00
Less 25%				\$ 6,421.50

SPECIAL NETT ITEM

NO	QTY	PARTS DISCRPTION	PART NO	PARTS PRICE
1	1	Rear windscreen moulding X		\$ 180.00
2	1	Rear windscreen sealant nee ✓		\$ 60 100.00
3	1	70km/hr sticker nee ✓		\$ 10 30.00
4	1	8pax sticker nee X		\$ 20 30.00
5	1	Rear end panel sealant nee ✓		\$ 60 100.00
6	1	Company logo sticker nee ✓		\$ 200 300.00
7	1	Reverse parking sensor nee ✓		\$ 200 280.00
Total SNett				\$ 1,010.00
parts & SNett				\$ 7,431.50

LABOUR FOR PANEL BEATING AND SPRAY PAINT

NO	LABOUR DISCRPTION	LABOUR PRICE
1	Labour for dismantle, panel beating, reshape and replacement tailgate assy, rear end panel, rear bumper and all affected areas	\$ 600 750.00
2	Labour for spray paint tailgate, end panel and all affected areas	\$ 500.00 ✓
3	Labour for replace and distance testing reverse sensor	\$ 60 80.00
4	Labour for remove and replace rear windscreen and conduct water leaking test	\$ 120 180.00
5	Labour for perform anti - rust teatment on affected areas	\$ 80 180.00
Total labour		\$ 1,690.00
Parts + labour		\$ 9,121.50
Total amount		\$ 10,811.50

We will carry out LUMP SUM repair on GBH8242A 3rd party claim

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

RASUL
Hp 90010068
6days
4/8
14/08/2020
@1280
Resurvey after repair
email: rasul@lkkauto.com