



TRANS EUROKARS PTE LTD

EUROKARS GROUP

ESTIMATE COST OF REPAIRS

EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block MND Complex, Singapore 069110 ATTN. : MOTOR CLAIMS FAX :	NAME : Exca Rental Pte. Ltd. ADDRESS : 38 Pioneer Sector 2 Singapore 628406 TEL : 85338460Richard	WIP : 16849 EXCESS : DATE: 11-Aug-20
--	--	--

VEH NO : SMA7122B	DATE IN :	CONTACT PERSON : Jess 8128 9802
CHASSIS NO : JM6BN24A8J0214793	MILEAGE :	TYPE OF CLAIM : THIRD PARTY CLAIM
MODEL : MAZDA 3	DATE REG. : 18-Jun-18	POLICY NO. :

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES
1 FRONT BUMPER <i>da /</i>	1		866.80
2 RETAINER LHS ?	1		15.50
3 RETAINER RHS ?	1		15.50
4 GROMMET, FRONT BUMPER <i>ne /</i>	2		5.80
5 FASTENER, FRONT BUMPER <i>ne /</i>	2		6.00
6 SEAL RUBBER, FRONT BUMPER <i>ne /</i>	2		4.80
7 FRONT REINFORCEMENT ?	1		502.80
8 STIFF 'A', FRONT BUMPER ?	1		87.90
9 RIVET, LICENCE PLATE HOLDER <i>ne /</i>	2		15.20
10 FRONT GRILLE <i>cm /</i>	1		135.50
11 BRACKET LHS, FRONT GRILLE ?	1		27.30
12 BRACKET RHS, FRONT GRILLE ?	1		27.30
13 CLIP, FRONT GRILLE <i>ne /</i>	1		3.40
14 CLIP, FRONT GRILLE <i>ne /</i>	2		9.40
15 PIN LOCATOR, FRONT GRILLE ?	2		5.80
16 GROMMET, FRONT GRILLE <i>ne /</i>	2		5.80
17 RIVET, FRONT GRILLE <i>ne /</i>	4		32.00
18 SEAL RUBBER, FRONT GRILLE <i>ne /</i>	2		5.60
19 PROTECTOR LHS, NO.1 ?	1		38.70
20 #REF! ?	1		39.10
21 PROTECTOR LHS, NO.2 ?	1		39.00
22 PROTECTOR RHS, NO.2 ?	1		39.00
23 PROTECTOR LHS, NO.3 ?	1		39.10
24 PROTECTOR RHS, NO.3 ?	1		39.00
25 PROTECTOR CENTER, NO.1 ?	1		71.00
26 PROTECTOR CENTER, NO.2 ?	1		71.00
27 PROTECTOR CENTER, NO.3 ?	1		69.70
28 PROTECTOR LHS, CHROME ?	1		20.50
29 PROTECTOR RHS, CHROME ?	1		20.50
30 CHROME LHS <i>cm /</i>	1		191.50

	CHROME RHS <i>crn /</i>	1	MB63B-50-7J1A		191.70
	MASCOT, FRONT <i>crn /</i>	1	MD10J-51-730		61.50
	BRACKET, MASCOT <i>ne /</i>	1	MB63B-50-716		21.70
34	GRILLE TOP <i>repm /</i>	1	MB63B-50-033A27		355.40
35	RIVET, GRILLE TOP <i>ne /</i>	4	MTK21-50-355		36.80
36	RIVET, GRILLE TOP <i>ne /</i>	4	MS51S-51-833		16.00
37	FASTENER, GRILLE TOP <i>ne /</i>	8	MGD7A-50-EA1		25.60
38	REAR BUMPER <i>de /</i>	1	MB63C-50-221ABB		997.50
39	BRACKET CENTER ? <i>ne /</i>	1	MKD53-50-251		5.40
40	GROMMET, REAR BUMPER <i>ne /</i>	4	MBHN1-50-0Z1A		10.80
41	RIVET, REAR BUMPER <i>ne /</i>	10	MBBM4-50-355		45.00
42	CLIP, REAR BUMPER <i>ne /</i>	2	MBGV4-56-145		5.80
43	FASTENER, REAR BUMPER <i>ne /</i>	2	MB45A-56-146A		6.00
44	RIVET, REAR BUMPER <i>ne /</i>	2	MEA01-50-037		16.00
45	TAPE PROTECTOR, REAR BUMPER <i>ne /</i>	2	MGS1D-50-EM1A		17.20
46	RETAINER CENTER, SENSOR ? <i>X</i>	2	MKD47-67-UC5A27		36.40
47	SENSOR, ULTRASONIC ?	2	MGMK6-67-UC1 27		361.80
48	COVER LHS, TOWING <i>mis /</i>	1	MB63B-50-EL1 BB		15.80
49	COVER RHS, TOWING <i>mis /</i>	1	MB63B-50-EK1 BB		15.80
50	REAR REINFORCEMENT ?	1	MB45C-50-260		564.20
51	TAILGATE <i>repm /</i>	1	MBHY3-62-02XA		1,332.20
52	FASTENER, TAILGATE <i>ne / X</i>	5	MGJ21-68-885B02		15.00
53	VALVE ONEWAY, TAILGATE <i>X</i>	2	MGHP9-58-867		24.00
54	FASTENER, REAR WINDSCREEN <i>X</i>	2	MBHS2-50-896		18.40
55	FASTENER, REAR WINDSCREEN <i>X</i>	2	MD204-50-896A		5.60
56	SPACER, REAR WINDSCREEN <i>X</i>	1	MGJ6A-50-897		12.80
57	ORNAMENT, MAZDA 3 <i>ne /</i>	1	MBHN9-51-721		56.10
58	ORNAMENT, SKYACTIVE <i>ne /</i>	1	MBHN9-51-771		66.80
59	MASCOT, REAR <i>ne /</i>	1	MBHN9-51-730		78.20
60	FASTENER, GARNISH <i>X</i>	2	MBHN9-50-EA1		5.80
61	PIN LOCATOR, GARNISH <i>X</i>	1	MBHN9-50-1K5		2.90
62	GASKET LHS, TAILLAMP <i>ne /</i>	1	MBHP1-51-163		22.00
63	GASKET RHS, TAILLAMP <i>ne /</i>	1	MBHP1-51-153		22.00
64	GASKET LHS, LAMP-TAILGATE <i>X</i>	1	MB45C-51-3J8		22.00
65	GASKET RHS, LAMP-TAILGATE <i>X</i>	1	MB45C-51-3H8		22.00
66	PROTECTOR, SPOILER <i>X</i>	4	MBHN9-51-979		19.20
67	PROTECTOR, SPOILER <i>X</i>	8	MBHP2-51-954		23.20
68	PROTECTOR, SPOILER <i>X</i>	2	MBHN9-51-954		18.60
69	CLIP, SPOILER <i>X</i>	1	MGB02-67-014		6.60
70	CLIP, SPOILER <i>X</i>	3	MB01A-51-958		10.80
71	GROMMET, SPOILER <i>X</i>	2	MBF67-51-261		4.80
72	FASTENER, SPOILER <i>X</i>	3	MEG21-51-146		18.60
73	PROTECTOR, SPOILER SIDE <i>X</i>	2	MBHN9-51-9B5		7.60
74	CLIP, SPOILER SIDE <i>X</i>	2	MEG21-51-SJ3		11.40
75	CLIP, SPOILER SIDE <i>X</i>	2	MKD53-51-0B6B		5.40
76	ANTENNA <i>X</i>	1	MKD47-67-6NXA		111.10
77	CLIP, ANTENNA <i>X</i>	1	MKD45-67-6NYA		2.70

RACKET TOP, GRILLE	X	1	MB63B-50-717		95.40
				TOTAL PARTS	7,298.10
				TOTAL PARTS COST	7,298.10

Labour Description

1	MZ-BR-FRONT3	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT AND GRILLE TOP. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	660	1,980.00
2	MZ-SP-SFRT03	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT AND GRILLE TOP.	780	1,890.00
3	MZ-BR-REAR04	TO REPLACE REAR BUMPER, REAR REINFORCEMENT AND TAILGATE. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	660	2,310.00
4	MZ-SP-SREAR4	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT AND TAILGATE.	1260	2,205.00
5	MZ-BR-SPOILER	TO REMOVE & REFIX SPOILER TAILGATE	NETT	X 180.00
6	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	NETT	X 560.00
7	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	NETT	X 120.00
8	MZ-BR-TAILME	TO TRANSFER TAILGATE MECHANISM.	X	330.00
9	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.		330.00
10	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	X	330.00
11	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	NETT	CA 70.00
12	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	250.00
13	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	450 X	250.00
14	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	350.00
15	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	NETT	X 100.00
16	MZ-BR-SUNDRI	SUNDRIES.	NETT	10 100.00
TOTAL LABOUR			-	11,355.00
TOTAL PARTS			-	7,298.10
TOTAL			-	18,653.10
LESS EXCESS			-	-

TOTAL AFTER EXCESS	-	
GST 7%	-	-
GRAND TOTAL	-	-

TRANS EUROKARS PTE LTD

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR

Authorised Signature

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resul
Hp 90010068
7 days
18/08/2020
@ 1400
Resurvey before paint