

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

VEHICLE NO : GBK1871P

MAKE & MODEL : TOYOTA HIACE VAN TURBO 5DR MT

CHASSIS NO : JTFHT02P000250043

DATE : 13 AUG 2020

CLAIM TYPE : TP CLAIM

D.O.A : 08 AUG 2020

TO : AIG ASIA PACIFIC INSURANCE PTE LTD L/S, RY AL 6 days

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT LIST PRICE	TOTAL LIST PRICE
1	1	REAR BUMPER	X	\$ 380.00	\$ 380.00
2	1	REAR BUMPER RETAINER LH	X	\$ 28.00	\$ 28.00
3	1	LH REAR FENDER PANEL	00	\$ 1,062.00	\$ 1,062.00
4	1	LH SLIDE DOOR	00	\$ 1,600.00	\$ 1,600.00
5	1	LH SLIDE DOOR WEATHERSTRIP	X	\$ 359.00	\$ 359.00
6	1	LH SLIDE DOOR LOCK REAR	X	\$ 280.00	\$ 280.00
7	1	LH SLIDE DOOR HINGE CENTER	X	\$ 150.00	\$ 150.00
8	1	LH SLIDE DOOR ROLLER LOWER	X	\$ 320.00	\$ 320.00
9	1	REAR WHEEL HUB CAP	MT	\$ 180.00	\$ 180.00
10	1	TAIL LAMP LH	X	\$ 260.00	\$ 260.00
				\$ 4,619.00	\$ 4,619.00

2812
- 25%
2109

TOTAL PRICE	\$ 4,619.00
LESS 25%	\$ 1,154.75
SUB TOTAL PRICE	\$ 3,464.25

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	SEALANT	MT	\$ 80.00	\$ 80.00
TOTAL S/NETT				\$ 80.00	\$ 80.00

Labour Charges

1	To cut & weld -damaged panels RH rear fender/	\$ 1,200.00	800
	To panel beat & align door, remove & replace damaged parts.		
2	To apply anti rust coat and Tuff Kote repaired areas	\$ 100.00	30
3	To check and rectify lighting & wiring.	\$ 100.00	30
4	To Spray painting for LH Portions, & affected areas.	\$ 1,000.00	450
5	To transfer slide door components.	\$ 150.00	50
6	To do tyre balancing & wheel alignment	\$ 150.00	60

TOTAL LABOUR

1470

\$ 2,700.00

Total Cost of Repairs

\$ 6,244.25

(Total parts + Total S/Nett + Total Labour Cost)

P- 2109
N- 30
L- 1420
3559

L/S- 2847.20
= 2850

LKK Auto Consultants hence notify the Reparer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company
Acknowledged by Reparer
Signature:
Date: