



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

Blk 1 Kaki Bukit Ave 6

12/08/2020

01-43

Singapore 417883

TP Lon Pac

Cecilie

Accident date: 12/08/2020

Estimated repair cost for vehicle no: SME4812S HONDA CIVIC 1.6 VTI CVT 18'

CHASSIS: MRHFC5650JT001359

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet <i>Dented</i>		\$581.30 ✓
2	2	Front Bonnet Hinge <i>New</i>	\$32.00	\$64.00 ✗
3	1	Front Bonnet Lock <i>New</i>		\$84.50 ✗
4	1	Front Grille		\$181.50 ✗
5	1	Front Grille Top Cover		\$23.00 ✗
6	1	Front Grille Center Moulding <i>New</i>		\$193.20 ✗
7	1	Front Grille Emblem Logo		\$27.40 ✗
8	6	Front Grille Clip	\$6.50	\$39.00 ✗
9	1	Front Grille Lower		\$96.20 ✗
10	1	Front Number Plate		\$50.00 ✗
11	1	Front R/H Door Side Mirror Assembly <i>cut</i>		\$807.50 ✓
12	1	Front R/H Door Side Mirror Cover (Bodykit) <i>New</i>		\$550.00 ✗
13	1	Front Support Panel <i>New</i>		\$574.50 ✗
14	1	Front Bumper (Bodykit) <i>torn</i>		\$3,000.00 1200 (sn) ✓
15	10	Front Bumper Clip <i>New</i>	\$6.50	\$65.00 30 ✓
16	1	Front Bumper Lower Lid (Bodykit) <i>cut</i>		\$850.00 500 (sn) ✓
17	1	Front R/H Bumper Side Retainer <i>New</i>		\$52.30 ✓
18	1	Front R/H Bumper Fog Lamp <i>New</i>		\$355.80 ✗
19	1	Front R/H Bumper Fog Lamp Cover <i>New</i>		\$45.20 ✗
20	1	Front R/H Headlamp <i>cut</i>		\$1,299.80 ✓
21	1	Front R/H Headlamp Lower Bracket <i>New</i>		\$39.00 ✗
22	1	Front R/H Headlamp Top Garnish <i>New</i>		\$105.80 ✗
23	1	Front R/H Fender <i>Distorted</i>		\$450.80 ✓
24	1	Front R/H Fender Moulding (Bodykit) <i>Debond</i>		\$350.00 250 (sn) ✓
25	1	Front R/H Fender Signal Lamp <i>cut</i>		\$36.20 ✓
26	1	Front R/H Fender Cowling <i>Debond</i>		\$85.80 ✓
27	6	Front R/H Fender Cowling Clip <i>New</i>	\$6.50	\$39.00 20 ✓
28	1	Front Wiper Tank <i>Deformed</i>		\$48.90 ✓

29	1	Front R/H Tyre <i>Purchased</i>		\$380.00 250(SN)
30	1	Front R/H Sport Rim <i>Cut</i>		\$1,200.00 750(SN)
31	1	Front R/H Lower Arm <i>Best</i>		\$291.40 ✓
32	1	Front R/H Knuckle Arm <i>Best</i>		\$241.40 ✓
33	1	Front R/H Knuckle Arm Bearing <i>Best</i>		\$190.60 ✓
34	1	Front R/H Shock Absorber <i>Best</i>		\$328.80 ✓
35	1	Front R/H Drive Shaft <i>Xbr New</i>		\$1,027.50 x
36	1	Front Steering Rack <i>Best</i>		\$2,598.80 1916 10
37	1	R/H Rocker Panel <i>Regis</i>		\$502.70 x
38	1	R/H Rocker Panel Skirt (Bodykit) <i>Cut</i>		\$900.00 680(SN)
39	12	R/H Rocker Panel Skirt Clip <i>New</i>	\$6.50	\$78.00 30
40	1	Front L/H Tyre <i>Purchased</i>		\$380.00 250(SN)
41	1	Front L/H Sport Rim <i>Cut</i>		\$1,200.00 750(SN)
42	1	L/H Rocker Panel <i>Regis</i>		\$502.70 x
43	1	L/H Rocker Panel Skirt (Bodykit) <i>Cut</i>		\$900.00 680(SN)
44	12	L/H Rocker Panel Skirt Clip <i>New</i>	\$6.50	\$78.00 30
45	1	Rear L/H Sport Rim <i>Cut</i>		\$1,200.00 750(SN)
46	1set	Type-R Body Kit <i>Xbr New</i>		\$8,000.00 x
47	1	Front L/H Lower Arm <i>Best</i>	291.40 ✓	
48	1	Front L/H Knuckle Arm <i>Best</i>	241.40 ✓	
49	1	Front L/H Knuckle Arm Bearing <i>Best</i>	190.60 ✓	
50	1	Front L/H Shock Absorber <i>Best</i>	328.80 ✓	
			Subtotal :-	<u>\$30,095.60</u>

7493.10

S-N 6060

5594.48

Labour charges

To remove & refit front L/H undercarriage	\$450.00 300
To remove & refit front R/H undercarriage	\$450.00 300
To remove & refit bodykit	\$350.00 X.
To check wiring	\$100.00 30
Towing fee	\$150.00 60
Tuff kote	\$120.00 50
Towing	\$150.00 X.
Panel beating	\$2,500.00 1000
Spray painting	\$2,000.00 1200

Subtotal :- \$6,270.00

Total:- \$36,365.60

total 14994.48

4/s: 12K

10 Days.

12K

10 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: