



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO20008434/Utf3s2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 02-09-2020		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 6053M	Veh. Inspected	SMR 4560A	
Policy No.	D20MTPCVE000064	Coverage (\$)	0.00	
Claim No.	CMTD2002357/GPL	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	17/08/2020	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 730LI (A)	c.c	2996	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WBAYE22060DZ20850	Colour	BEIGE	
Odometer	46259	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/50 R18	TOYO	6 mm	
L/H Front Tyre	245/50 R18	TOYO	6 mm	
R/H Rear Tyre	245/50 R18	TOYO	6 mm	
L/H Rear Tyre	245/50 R18	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/08/2020	Inspection Date	17/08/2020	
Survey held at	STK AUTO (S) PTE LTD 8 KAKI BUKIT AVE 4 #03-21 PREMIER@KAKI BUKIT SSINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		