

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 20 Aug 2020

Preliminary Advice

Insured Vehicle No	: SKL9311A		
TP Vehicle No	: SMF217G	Accident Date	: 08/08/2020
Make	: MAZDA MAZDA5	Assignment Date	: 14/08/2020
Date of Inspection	: 19/08/2020	Est. Duration of Repair	: 1
Inspection At	: EUROKARS SERVICES PTE LTD (HQ) 27A TANJONG PENJURU SINGAPORE 609042		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,963.30
Revised Amount	:S\$	1,094.18
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,094.18

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : survey on wp