

ADVANCE AUTO GARAGE

10 Kaki Bukit Road 2
FIRST EAST CENTRE
#01-21 SINGAPORE 417868
Tel: +65 9007 9247
Email: advanceag@hotmail.com
Reg No: 53395571L

TO	: AXA	DATE	: 12/8/2020
ATTENTION	: MOTOR INSURANCE CLAIM	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT			
VEHICLE DETAILS			
VEHICLE NO	: SBU2933K	TP AXA - Cecilia.	
VEHICLE MODEL	: HONDA VEZEL HNYBRID		
CHASSIS NO	:		
ACCIDENT DETAILS	DATE	: 11/8/2020	
	TIME	: 08:50PM	
THIRD PARTY REQUESTOR / CONTACT	: XAVIER		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR TAILGATE <i>tested</i>	1	\$ 1,132.90	\$ 1,132.90
2	REAR TAILGATE HINGE <i>new</i>	2	\$ 70.00	\$ 140.00
3	REAR TAILGATE ABSORBER <i>changed</i>	2	\$ 220.00	\$ 440.00
4	REAR TAILGATE LOGO <i>new</i>	1	\$ 80.00	\$ 80.00
5	REAR TAILGATE EMBLEM "VEZEL" <i>new</i>	1	\$ 80.00	\$ 80.00
6	REAR TAILGATE INNER TRIM BOARD <i>behind</i>	1	\$ 286.40	\$ 286.40
7	REAR TAILGATE INNER HANDLE <i>new</i>	1	\$ 60.00	\$ 60.00
8	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 120.00	\$ 120.00
9	TAILGATE WEATHER STRIPE <i>lt</i>	1	\$ 180.00	\$ 180.00
10	REAR NUMBER PLATE GARNISH <i>new</i>	1	\$ 255.00	\$ 255.00
11	REAR NUMBER PLATE LAMP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
12	TAILGATE LOCK <i>changed</i>	1	\$ 187.00	\$ 187.00
13	TAILGATE LOCK CATCH <i>new</i>	1	\$ 45.00	\$ 45.00
14	REAR BUMPER (CENTRE) <i>behind</i>	1	\$ 846.80	\$ 846.80
15	REAR BUMPER (CENTRE) RETAINER <i>new</i>	2	\$ 60.00	\$ 120.00
16	REAR BUMPER REFLECTOR <i>RA changed</i>	2	\$ 226.10	\$ 452.20
17	REAR SIDE BUMPER PIECE <i>new</i>	2	\$ 285.00	\$ 570.00
18	REAR SIDE BUMPER RETAINER <i>new</i>	2	\$ 60.00	\$ 120.00
19	REAR END PANEL <i>tested</i>	1	\$ 563.70	\$ 563.70
20	REAR END PANEL TOP GARNISH <i>behind</i>	1	\$ 180.00	\$ 180.00
21	SMART ADAPTER <i>new</i>	1	\$ 87.00	\$ 87.00

TOTAL PRICE: \$ 6,006.00

~~center beam~~

rear absorber bumper

Best

1 3687.50 490.

4987.50

3990.32

LESS 20% \$ 1,201.20
SUB TOTAL PRICE: \$ 4,804.80

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE <i>Neu</i>	1	\$ 50.00	\$ 50.00
2	REVERSE SENSOR <i>Daeng</i>	4	\$ 135.00	\$ 540.00
3	REAR BUMPER CLIP (SET) <i>an</i>	3	\$ 20.00	\$ 60.00
4	REAR END PANEL TOP GARNISH CLIP (SET) <i>an</i>	1	\$ 20.00	\$ 20.00
5	TAILGATE INNER TRIM BOARD CLIP (SET) <i>an</i>	3	\$ 20.00	\$ 60.00
6	REAR NUMBER PLATE GARNISH CLIP (SET) <i>Neu</i>	1	\$ 20.00	\$ 20.00
7	REAR TAILGATE SCREWS (SET) <i>Neu</i>	3	\$ 20.00	\$ 60.00
8	REAR OUTER TAIL LIGHT (LED) <i>Fit could</i>	2	\$ 950.00	\$ 1,900.00
9	REAR TAIL GATE REFLECTOR (LED) <i>Fit could</i>	2	\$ 500.00	\$ 1,000.00
10	REAR AUTO TAIL GATE MOTOR (SET) <i>Neu damaged</i>	1	\$ 1,650.00	\$ 1,650.00
11	REAR BUMPER CARBON FIBRE STICKER <i>Neu</i>	1	\$ 100.00	\$ 100.00
12	REAR BUMPER CARBON FIBRE ADD ON LIP <i>Dehnd</i>	1	\$ 450.00	\$ 450.00
13	REVERSE CAMERA <i>Neu</i>	1	\$ 550.00	\$ 550.00
14	REAR END PANEL INSULATION SEAL <i>Neu</i>	1	\$ 100.00	\$ 100.00

Tailgate Sand Proof

Neu

256

200

TOTAL : \$ 6,560.00

2390

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,600.00	<i>800</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	<i>700</i>	
3	LABOUR TO TRANSFER REVERSE CAMERA	\$ 200.00	<i>50</i>	
4	WIRING CHECK	\$ 100.00	<i>30</i>	
5	TUFF COAT	\$ 120.00	<i>60</i>	
6	LABOUR TO REMOVE AND REFIT TAILGATE MECHANISM	\$ 200.00	<i>80</i>	
7	LABOUR TO REMOVE AND REFIT REAR WINDSCREEN	\$ 200.00	<i>120</i>	
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 100.00	<i>50</i>	
9	WATER LEAKAGE TEST	\$ 80.00	<i>X</i>	
10	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATIONS	\$ 300.00	<i>X</i>	

1890

TOTAL: \$ 4,500.00

ESTIMATE REPORT

TOTAL PARTS COST:	\$	11,364.80
TOTAL LABOUR COST:	\$	4,500.00
TOTAL REPAIR COST:	\$	15,864.80

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

total: 127032
4/5: 6.6K.
06 Days

G-6K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: