

# FormTeam Consultancy Pte Ltd

No. 33 Ubi Ave 3  
#02-15 Vertex  
Singapore 408868

Tel: (65) 6509 1788  
Fax: (65) 6509 6221

Email: [motorsurvey@fta.com.sg](mailto:motorsurvey@fta.com.sg)  
[www.fta.com.sg](http://www.fta.com.sg)

Co. Reg No: 200819280D  
GST Reg. No: 200819280D

## Immediate Advice

To : AXA Insurance Date : 29.06.2019  
Attention : Mr Chen Xinyou Our Ref : AXA19-064126/PRS/GS

### A. Particulars

Vehicle No. : SJY 6546C Accident Date : 21.06.2019  
Make/Model : Volkswagen Scirocco Your Ref : S9M01S2D  
Claim Type : PRS Policy No : -  
Excess : - Date Survey : 28.06.2019 @1045hrs  
The vehicle was inspected at the premise of M/s Hua Meng Spray Painting

### B. Details

Please be informed that we have / ~~have not~~ conducted the inspection of the abovementioned and have the followings to report:-

Estimate by Repairer (S\$) : 0.00  
Our Revised Estimate (S\$) : 0.00  
Exclude 'check' items of (S\$) : 0.00 (Subject to confirmation)

### C. Remarks

- ( ) The vehicle has not been sent in for repair  
( ) We are checking the vehicle whether it is economical to repair  
( ) The vehicle 'may not be' / is economical to repair  
( ) The repairer cannot repair this vehicle on a Lump Sum basis due to unavailability of second hand parts / awaiting for your approval to allow the repairer to repair this damaged vehicle on a 'Part By Part' basis  
( X ) Market Value of vehicle is estimated at S\$ 23,800.00  
( X ) Salvage Value including OMV & COE S\$ 17,300.00  
( X ) Net Loss of vehicle is S\$ 6,500.00  
( ) We have not authorize repair, waiting for your authorization

We thank you for your instruction.



Gary Soon  
Automobile Appraiser  
Email: [motorsurvey@fta.com.sg](mailto:motorsurvey@fta.com.sg)

#### Remarks:-

There was no estimate provided by repairer. In our opinion, the estimated repair cost at Lump sum \$4,000.00 @ 05 repair days.







































