

# PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883  
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Invoice No 06-19037/DY

Billing Name & Address

Roseda Binte Hassan  
c/o No. 1 Kaki Bukit Avenue 6  
#01-61/34 AutoBay @ Kaki Bukit  
Singapore 417883

Date 16 Jul 2019

Vehicle No : SJY 6546 C

Model : Volkswagen Scirocco

Item	Descriptions	Amount S\$
1	Date of inspection : <u>28 Jun 2019</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Purchase of films, develop negatives - Storage of negatives - Submission of photographs <u>84</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 684.00</u>
	SDLS : SIX HUNDRED AND EIGHTY-FOUR ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Pal's Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O. E

# PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883

Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference : **TP / 06-19037/DY / 2019**

Date of Report : **16 Jul 2019**

Roseda Binte Hassan  
c/o No. 1 Kaki Bukit Avenue 6  
#01-61/34 AutoBay @ Kaki Bukit  
Singapore 417883

## THIRD PARTY SURVEY

**ACCIDENT HAPPENED ON 21 Jun 2019**

As per your instruction dated **28 Jun 2019** with regard to the above matter. We have carried out a physical inspection on the said vehicle **SJY 6546 C**. We enclosed herewith our report and findings as follows:

### 1. VEHICLE PARTICULARS

Registration No : SJY 6546 C  
Model : Volkswagen Scirocco  
Year / Capacity : 2010/1390  
Chassis No : WVWZZZ13ZBV004655  
Engine No : CAV211307  
Mileage : 156413  
Colour : White

### 2. TYRES CONDITION

			<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	:	235/65 R19	Michelin	7.00	mm	Sport
REAR	O/S	:	235/65 R19	Michelin	7.00	mm	Sport
FRONT	N/S	:	235/65 R19	Michelin	7.00	mm	Sport
REAR	N/S	:	235/65 R19	Michelin	7.00	mm	Sport

# PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883  
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

### 3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the front o/s portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Hua Meng Spray Painting Workshop  
No. 1 Kaki Bukit Avenue 6  
#01-61/34 AutoBay @ Kaki Bukit  
Singapore 417883

5. Estimated normal period of repair : 4 working days to complete.

6. Enclosed number of photograph : 84 copies.

7. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.

8. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

#### Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: **SJY 6546 C**  
 Report No: **TP/ 06-19037/DY / 2019**

**SPARE PARTS**

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Front headlamp	Damage	\$ 845.00	\$ 845.00
1	Front bumper fog lamp	Intact	\$ 400.00	\$
1	Front bumper reinforcement	Intact	\$ 687.00	\$
1	Front bumper side retainer	Damage	\$ 35.00	\$ 35.00
1	Front fender	Damage	\$ 670.00	\$ 670.00
1	Front fender inner shield	Damage	\$ 189.00	\$ 189.00
1	Front wheel hub with bearing	Necessary	\$ 285.00	\$ 285.00
1	Front shock absorber	Damage	\$ 485.00	\$ 485.00
1	Front knuckle arm	Damage	\$ 655.00	\$ 655.00
1	Front lower arm	Damage	\$ 240.00	\$ 240.00
1	Front lower arm ball joins	Damage	\$ 78.00	\$ 78.00
1	Front o/s side mirror	Damage	\$ 882.70	\$ 882.70
			<u>\$ 5451.70</u>	<u>\$ 4364.70</u>
	Discount	10.0%	\$ 545.17	\$ 436.47
			<u>\$ 4906.53</u>	<u>\$ 3928.23</u>
<u>Special Nett Items</u>				
1	Front bumper	Damage	\$ 1800.00	\$ 1800.00
1	Front fender inner shield clip (1 set)	Necessary	\$ 30.00	\$ 30.00
1	Front tyre (Depreciation)	Damage	\$ 380.00	\$ 266.00
1	Front sport rim	Damage	\$ 650.00	\$ 650.00
			<u>\$ 2860.00</u>	<u>\$ 2746.00</u>

**Spare Parts Total**     \$ 7766.53     \$ 6674.23

Vehicle No: **SJY 6546 C**  
Report No: **TP/ 06-19037/DY / 2019**

**LABOUR COST**

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 7766.53	\$ 6674.23
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 60.00	\$ 40.00
2	To remove and refit front undercarriage.	\$ 280.00	\$ 200.00
3	To check and re-adjust (Computerized) all wheel alignment.	\$ 180.00	\$ 120.00
4	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 700.00	\$ 440.00
5	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 650.00	\$ 440.00
6	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 120.00	\$ 30.00
<b>Total</b>		<u>\$ 9756.53</u>	<u>\$ 7944.23</u>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

**\$ 6400.00**

SDLS: SIX THOUSAND FOUR HUNDRED ONLY

  
\_\_\_\_\_  
Qualified Appraiser













































































