

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 44713

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0559/2020/NS
Date : 12-Aug-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Li Yuanfang
Address : Blk 339B Kang Ching Road
#08-326
Singapore 612339
Telephone : HP +65 96289276
Type of Claim : Own Damage Claim
Policy No. : 1800143196-01
Vehicle No : **SMF 9486 L**
Model Code : Audi A3 sportsback 1.0 TFSI
Model / Year : Nov-19
Engine No : CHZ B22242
Chassis No : WAUZZZ8V6KA008776
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 30-Jul-20
Place of Accident : 311A Clementi Ave 4

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMF 9486 L

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer/reinstall front bumper wire harness for front parking aid system.	S/N \$ 280.00 X	
2	To dismantle and renew front bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 1,050.00 500 ✓	✓
3	To respray front bumper.	\$ 900.00 550 ✓	✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: <u>\$ 2,422.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 9486 L

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>rehd</i>	\$ 1,842.00 ✓	1473.60
2	FRONT BUMPER FIXING PARTS <i>neu</i>	\$ 185.00 +	
3	FRONT BUMPER GRILLE - CENTRE <i>neu</i>	\$ 159.00 +	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>neu</i>	\$ 293.00 +	
5	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>neu</i> 2	\$ 586.00 +	
6	RADIATOR GRILLE <i>ut</i>	\$ 1,406.00 ✓	1124.80
7	RADIATOR GRILLE CLOSING ELEMENT ?	\$ 189.00 ?	X NN
8	AIRCON STICKER <i>extra</i>	NEC \$ 8.00 ✓	5.68
9	CAUTION SIGN STICKER	NEC \$ 14.00 ✓	10.80
10	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>neu</i> 2	\$ 372.00 +	
11	FRONT BUMPER SIDE REINFORCEMENT BEAM ?	\$ 715.00 ?	X NN
12	FRONT BUMPR FOAM FILLER PIECE ?	\$ 187.00 ?	X NN
13	FOAM FILLER PIECE COVER ?	\$ 121.00 ?	X NN
14	RADIATOR AIR GUIDE - LH / RH <i>neu</i> 2	\$ 48.00 +	
15	FRONT NO PLATE <i>neu</i>	S/N \$ 60.00 ✓	✓
16	SUNDRIES	\$ 200.00 ?	X NN
TOTAL SPARE PARTS CHARGES		: \$ 6,385.00	
TOTAL LABOUR CHARGES		: \$ 2,422.00	
GRAND TOTAL		: \$ 8,807.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 13/08/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant