

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 44711

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0560/2020/NS
Date : 12-Aug-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian,
3 days - ok - Jy - 01 Dec 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Li Yuanfang
Address : Blk 339 Kang Ching Road
#08-326
Singapore 612339
Telephone : HP +65 96289276
Type of Claim : Own Damage Claims
Policy No. : 1800143196-01
Vehicle No : **SMF 9486 L**
Model Code : Audi A3 SPORTSBACK 1.0 TF
Model / Year : Nov-18
Engine No : CHZ B22242
Chassis No : WAUZZZ8V6KA008776
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Aug-20
Place of Accident : Sims Edge 1 Geylang East Ave 2

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMF 9486 L

S/N	Nature of Jobs		Estimated Charges		Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N	\$ 280.00	\$	280.00
2	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio components.	S/N	\$ 480.00	\$	480.00
3	To dismantle and renew rear bumper. To cut out and reweld rear end panelling outer and inner. Re-organise crash management components. Reinstall all parts removed.		\$ 3,500.00	\$	500.00
4	To respray rear bumper, lhs rear fender and end panelling. To carry out joint sealer works and stone chip treatment.		\$ 3,000.00	\$	550.00
5	To renew lhs rear exhaust silencer. To align to psition.	S/N	\$ 480.00		
6	To carry out diagnostic check.	S/N	\$ 192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 7,932.00	\$	2,002.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 9486 L

S/N		Parts Description		Damage Parts & Prices		
				S/NETT		Remarks
1		REAR BUMPER	\$	1,847.00	\$	1,477.60
2		REAR BUMPER FIXING PARTS	\$	191.00		
3		REAR BUMPER LOCKING MECHANISM - LH / RH	2 \$	28.00		
4		WHEEL HOUSING LINER ADAPTER - LH / RH	\$	37.00		
5		REAR BUMPER SPOILER	\$	234.00		
6		REAR LIGHT REFLECTOR - LH	\$	30.00		
7		LED TAIL LIGHT - LH	\$	867.00		
8		REAR BUMPER SIDE REINFORCEMENT BEAM	\$	565.00	\$	451.60
9		REAR BUMPER BRACKET - LH	\$	27.00		
10		REAR BUMPER BRACKET - RH	\$	28.00		
11		REAR BUMPER GUIDE SECTION - LH	\$	66.00	\$	52.40
12		REAR PARKING AID SENSOR - INNER / OUTER	2	TBC		
13		CROSS PANEL REINFORCEMENT	\$	725.00		
14		REAR CROSS PANEL	\$	242.00		
15		REAR SILENCER	\$	615.00		
16		REAR SILENCER DUAL CLIP	\$	57.00		
17		EXHAUST SYSTEM RETAINER	2 \$	79.00		
18		AUDI EMBLEM	\$	122.00		
19		A3 INSCRIPTION	\$	95.00		
20		PACKING ADHESIVE	\$	18.00		
21		STONE CHIP	S/N \$	180.00		
22		CAVITY WAX	S/N \$	140.00		
23		ACRYLIC SEALANT	S/N \$	180.00		
24		SUNDRIES	\$	300.00	\$	69.28
TOTAL SPARE PARTS CHARGES			:	\$ 6,673.00	\$	2,050.88
TOTAL LABOUR CHARGES			:	\$ 7,932.00	\$	2,002.00
GRAND TOTAL			:	\$ 14,605.00	\$	4,052.88

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

BL-22/10/20

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant