

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722
Tel: 8269-9999 Email: estimate.tap@gmail.com / teamautopro@gmail.com

S/E : _____ Vehicle Nos : **SIL 7135 S**
Date of Survey : _____ Made : Mazda
Date of ReSurvey : _____ After-Paint: _____ Model : S
Contacts : _____ Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with S/E ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit \$	TOTAL \$	
1	Tailgate	1	\$ 2,827.50	\$ 2,827.50	EX CUT
2	Tailgate logo	1	\$ 84.30	\$ 84.30	NEG
3	Tailgate emblem 'MAZDA'	1	\$ 52.80	\$ 52.80	NEG
4	Tailgate emblem 'S'	1	\$ 32.00	\$ 32.00	✓
4	Tailgate inner trim board	1	\$ 1,248.60	\$ 1,248.60	NDX
5	Tailgate inner lock	1	\$ 286.30	\$ 286.30	DP ✓
6	Tailgate inner lock sticker	1	\$ 48.00	\$ 48.00	NDX
7	Tailgate windscreen moulding	1	\$ 297.80	\$ 297.80	NSX
8	Rear bumper	1	\$ 899.30	\$ 899.30	BRX ✓
9	Rear bumper bracket	2	\$ 52.10	\$ 104.20	NNX
10	Rear bumper side retainer	2	\$ 38.40	\$ 76.80	NEG ✓
11	Rear bumper reinforcement	1	\$ 358.60	\$ 358.60	DP ✓
12	Rear bumper reflector	2	\$ 63.00	\$ 126.00	BRX ✓
13	Rear bumper lower spoiler	1	\$ 523.10	\$ 523.10	NDX
14	Rear end panel	1	\$ 686.36	\$ 686.36	DP ✓
15	Rear end panel top garnish	1	\$ 248.60	\$ 248.60	DP ✓
16	Rear fender RH	1	\$ 1,842.30	\$ 1,842.30	NDX
17	Rear fender inner cowling RH	1	\$ 320.40	\$ 320.40	NDX
18	Tailamp RH	1	\$ 537.80	\$ 537.80	BRX ✓
				Parts Sub Total :	\$ 10,737.36
				Discount 20%	\$ 2,147.47
				PARTS TOTAL :	\$ 8,589.89

20% Discount
3048.80
609.76
2439.04

Nos.	SPECIAL NETT	Qty	Unit	SS	TOTAL SS	
1	Sundries	1	\$	80.00	\$	80.00
2	Tailgate inner trim board clips	1	\$	50.00	\$	50.00
3	Tailgate windscreen inner seal	1	\$	80.00	\$	80.00
4	Tailgate windscreen sealant	1	\$	100.00	\$	100.00
5	Tailgate windscreen primer and cleaner	1	\$	120.00	\$	120.00
6	Rear bumper clips	1	\$	50.00	\$	50.00
7	Rear bumper side skirts clips	1	\$	50.00	\$	50.00
8	Rear end panel sealant	1	\$	100.00	\$	100.00
9	Rear end panel top garnish clips	1	\$	50.00	\$	50.00
10	Rear fender sealant	1	\$	100.00	\$	100.00
11	Rear fender inner cowlings clips	1	\$	50.00	\$	50.00
12	Tail lamp seal	1	\$	60.00	\$	60.00
13	Tail lamp clips	1	\$	50.00	\$	50.00
14	Reverse camera	1	\$	480.00	\$	480.00
15	Reverse sensor w/module	2	\$	250.00	\$	500.00
SPECIAL NETT TOTAL:					\$	1,920.00

Nos.	LABOUR	SS	
1	R&A tailgate component	\$	150.00
2	R&A tailgate windscreen	\$	200.00
3	R&A reverse sensor	\$	60.00
4	R&A reverse camera	\$	60.00
5	Upholstery	\$	400.00
6	Check wiring	\$	60.00
7	Panel beat	\$	600.00
8	Rust proofing	\$	60.00
9	Spray paint	\$	600.00
LABOUR TOTAL:		\$	3,910.00

PARTS TOTAL:	\$	8,589.89
SPECIAL NETT TOTAL:	\$	1,920.00
LABOUR TOTAL:	\$	3,910.00
GRAND TOTAL:	\$	14,419.89

PARTS 2439.04
 S/N 530.40
 LABOUR 1440.00
 @ 20% 4469.04
 893.81
 3575.23

L/S 3550/2

Terim M
 20/8/2020

Terim M
 Survey Reserve
 13/8/2020 17/8/2020
 14/8/2020 14/30/2020

Repair days 5
 Lump sum repair

LKX Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged parts during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No legal modifications is allowed
 • Supplementary items must be resurveyed and
 is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature
 Date