



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III20000310/Gtf3e2-1

64 CECIL STREET  
#05-02 IOB BUILDING SINGAPORE 049711

Date : 20-08-2020



Code : III2

#### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |             |                |            |
|--------------|-------------|----------------|------------|
| Insured Veh. | SHA 4543Z   | Veh. Inspected | SKD 5670G  |
| Policy No.   | MCOM0015    | Coverage (\$)  | 0.00       |
| Claim No.    | MCT20010013 | Excess (\$)    | 0.00       |
| Assign From  | CARINE KEK  | Assign Date    | 14/08/2020 |

#### 2. Vehicle Particulars & Condition

|              |                     |              |            |
|--------------|---------------------|--------------|------------|
| Make & Model | AUDI A6 2.0 TFSI MU | c.c          | 1984       |
| Engine No.   | HIDDEN              | Year of Reg. | 2011       |
| Chassis No.  | WAUZZZ4G1CN021212   | Colour       | GREY       |
| Odometer     | 240708              | Steering     | IN ORDER   |
| Brakes       | IN ORDER            | Modification | SPORTS RIM |
| General      | GOOD                |              |            |

#### 3. Conditions of Tyres

|                | Size       | Make    | Balance |
|----------------|------------|---------|---------|
| R/H Front Tyre | 225/55 R17 | PIRELLI | 7 mm    |
| L/H Front Tyre | 225/55 R17 | PIRELLI | 7 mm    |
| R/H Rear Tyre  | 225/55 R17 | PIRELLI | 7 mm    |
| L/H Rear Tyre  | 225/55 R17 | PIRELLI | 7 mm    |

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

#### 5. General Information

|                |  |                 |            |
|----------------|--|-----------------|------------|
| Accident Date  | 01/01/2020   | Inspection Date | 13/01/2020 |
| Survey held at | A.S.AUTO SERVICE<br>NO.1 KAKI BUKIT AVE 6<br>#01-106<br>SINGAPORE 417883 |                 |            |

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 4 Working Days |
|-------------------------------------|----------------|