

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 45481

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0573/2020/NS
Date : 15-Aug-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian,

6 days - ok - Jy - 7 Nov 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Ang Yoke Pheng
Address : 5C Chancery Hill Road
Singapore 309647
Telephone : Office +65 98399366
Type of Claim : Own Damage Claims
Policy No. : 1800115567
Vehicle No : **SDS 5525 Y**
Model Code : Audi Q2 1.0 TFSI S TRONIC
Model / Year : Sep-18
Engine No : CHZ A90358
Chassis No : WAUZZZGA5KA000621
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Aug-20
Place of Accident : Dunearn Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDS 5525 Y

S/N	Nature of Jobs		Estimated Charges		Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	280.00	\$	280.00
2	To remove and transfer both headlight control units and power modules.	S/N \$	800.00		
3	To remove and renew aircon condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,400.00	\$	1,400.00
4	To dismantle and renew front bumper and both headlights. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$	4,000.00	\$	1,750.00
5	To respray front bumper.	\$	1,200.00	\$	550.00
	SUPPLEMENTARY	\$	1,000.00	\$	500.00
6	To carry out diagnostic check.	S/N \$	192.00	\$	192.00
	TOTAL LABOUR CHARGES	:	\$ 8,872.00	\$	4,672.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDS 5525 Y

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,854.00	\$ 1,482.00
2	FRONT BUMPER FIXING PARTS	\$ 343.00	
3	FRONT BUMPER GRILLE - CENTRE	\$ 195.00	
4	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$ 334.00	\$ 133.60
5	FRONT BUMPER END CAP - LH / RH	2 \$ 68.00	
6	FRONT BUMPER SPOILER	\$ 296.00	\$ 236.40
7	FRONT BUMPER CLOSING ELEMENT	\$ 154.00	
8	FRONT WHEEL SPOILER - LH / RH	2 \$ 68.00	
9	RADIATOR GRILLE	\$ 1,395.00	\$ 1,116.00
10	RADIATOR GRILLE STRIKER PLATE	\$ 123.00	
11	FRONT BUMPER CARRIER	\$ 679.00	
12	FRONT BUMPER FOAM FILLER PIECE	\$ 77.00	\$ 61.20
13	FOAM FILLER PIECE COVER	\$ 99.00	
14	FRONT BUMPER GUIDE SECTION - LH / RH	2 \$ 70.00	
15	AIRCON STICKER	NEC \$ 8.00	
16	CAUTION SIGN STICKER	NEC \$ 14.00	
17	WHEEL HOUSING LINER - LH / RH	2 \$ 388.00	
18	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 57.00	
19	HEADLIGHT MOUNTING - LH / RH	2 \$ 234.00	
20	LED HEADLIGHT - LH / RH	2 \$ 9,718.00	
SUB TOTAL SPARE PARTS CHARGES		\$ 16,174.00	\$ 3,029.20

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDS 5525 Y

S/N	Parts Description		Damage Parts & Prices		REMARKS
			S/NETT		
		<i>c/f</i>			\$ 3,029.20
21	LIFT CYLINDER - LH / RH	2	\$	282.00	
22	LIFT CYLINDER HOSE		\$	175.00	
23	LOCK CARRIER		\$	983.00	
24	AIRCON CONDENSER		\$	545.00	\$ 436.00
25	EXTERNAL TEMPERATURE SENSOR		\$	56.00	
26	READY MIX COOLANT		\$	177.00	\$ 141.44
27	RADIATOR AIR GUIDE - LH / RH	2	\$	60.00	\$ 23.92
28	RADIATOR AIR GUIDE - UPPER CENTRE		\$	22.00	\$ 17.04
29	FRONT WHEEL COVER - LH / RH	2	\$	636.00	\$ 508.80
30	FRONT NO PLATE	S/N	\$	60.00	\$ 60.00
31	SUPPLEMENTARY		\$	617.00	\$ 493.60
32	SUNDRIES		\$	300.00	\$ 11.92
TOTAL SPARE PARTS CHARGES			:	\$ 20,087.00	\$ 4,721.92
TOTAL LABOUR CHARGES			:	\$ 8,872.00	\$ 4,672.00
GRAND TOTAL			:	\$ 28,959.00	\$ 9,393.92

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0573/2020/NS 18-Aug-20 Glory Tan 1 OF 1 SDS 5525 Y Audi Q2 1.0 TFSI S TRONIC
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Rear bumper lower spoiler.	\$ 281.00	\$ 224.80
2	Rear wheel arch trim LHS	\$ 168.00	\$ 134.40
3	Rear wheel arch trim RHS	\$ 168.00	\$ 134.40
			\$ 493.60
<u>Labours</u>			
1	To remove and reinstall rear bumper. To renew rear bumper lower spoiler.	\$ 1,000.00	\$ 500.00
TOTAL		\$ 1,617.00	\$993.60

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant