

**Shirley Hiew (LKK Auto)**

---

**From:** Shirley Hiew (LKK Auto)  
**Sent:** Tuesday, 25 August 2020 6:21 pm  
**To:** Rasul (LKKAuto)  
**Cc:** SUR  
**Subject:** RE: SDS5525Y

Hi Rasul,

Please submit the photo in Merimen.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.**

---

**From:** Rasul (LKKAuto) <Rasul@lkkauto.com>  
**Sent:** Tuesday, 25 August 2020 6:05 pm  
**To:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Subject:** RE: SDS5525Y

Hi Shirley,

The front spoiler cracked

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

Best Regards,  
**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



---

**From:** Shirley Hiew (LKK Auto)  
**Sent:** Tuesday, 25 August, 2020 5:35 PM  
**To:** Rasul (LKKAuto)  
**Cc:** SUR  
**Subject:** FW: SDS5525Y

**Urgent**

Hi Rasul,

Kindly assist below email from AIG.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.**

---

**From:** Koh, Victor-CK <[Victor-CK.Koh@aig.com](mailto:Victor-CK.Koh@aig.com)>  
**Sent:** Tuesday, 25 August 2020 3:49 pm  
**To:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** SDS5525Y

Hi,

FRONT BUMPER SPOILER- damage photos?

Thanks & Regards

**Victor Koh**  
**AIG**

Claims Technical Controller  
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120  
Tel +65 6419 1785 | Fax +65 68357416  
[Victor-ck.koh@aig.com](mailto:Victor-ck.koh@aig.com) | [www.aig.com](http://www.aig.com)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.