LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building, 78 Shenton Way

#09-16

Chan, Yoke Shi

Attn:

Singapore 079120

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Date: 18 Aug 2020

Preliminary Advice

Vehicle No : SDS5525Y Accident Date : 14/08/2020 Make : AUDI Q2 Policy No. : 1800115567 **Assignment Date** : 17/08/2020 **Excess** : S\$0.00 Date of Inspection : 17/08/2020 Est. Duration of Repair : 3

Inspection At : PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1 SINGAPORE 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,342.00
Revised Amount	:S\$	5,930.00
Check Items (Estimated)	:S\$	15,052.00
Total	:S\$	20,982.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 94,000.00 COE / PARF Rebate 43,375.00 :S\$

Salvage Value :S\$

Margin for Repair 50,625.00 :S\$

Remarks

()	()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :