

Date: 20.08.2020

Vehicle No: SMQ6040B

Model: TOYOTA NOAH 1.8X

Chassis: ZWR800401703 - 2019

Reg.Year: 2019

Third Party Insurer:

CHINA TAIPING

Third Party Veh No:

SJY6486S

Date of Accident:

13.08.2020

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR SPARE TYRE UPPER BOARD <i>845.10</i>	1		<i>CM</i> \$1,005.60 ✓
2	REAR TAILGATE INNER TRIM COVER <i>371.35</i>	1		<i>BU</i> \$570.50 ✓
SUB TOTAL				\$1,576.10
LESS 25%				-\$394.03
PARTS TOTAL				\$1,182.08

6261.06

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date: 15.08.2020
Vehicle No: SMQ6040B
Model: TOYOTA NOAH 1.8X
Chassis: ZWR800401703 - 2019
Reg.Year: 2019

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SJY6486S
Date of Accident: 13.08.2020

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC.
BACK TO ORIGINAL OPERATIONS.

60/
\$120.00

LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR & ETC.
TO EFFECT REPLACE OF REAR BUMPER.

\$100.00 50/

TO CHECK WIRING & TAILGATE CENTRAL LOCKING SYSTEM & ETC.
BACK TO ORIGINAL OPERATIONS.

30/
\$100.00

LABOUR TOTAL \$1,870.00

TINGAN

TOTAL \$5,078.98

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

452 Tagore Industrial Avenue Singapore 787823
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date: 15.08.2020

Vehicle No: SMQ6040B

Model: TOYOTA NOAH 1.8X

Chassis: ZWR800401703 - 2019

Reg.Year: 2019

Third Party Insurer: CHINA TAIPING

Third Party Veh No: SJY64865

Date of Accident: 13.08.2020

Not Authorised

Running B4 permit

84985.05

4 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE 1712.85	1		Ry \$1,788.80
2	REAR TAILGATE "HYBRID" EMBLEM	1		nn \$95.80
3	REAR TAILGATE INNER TRIM CLIPS	8	\$5.50	nn \$44.00
4	REAR TAILGATE RUBBER	1		Di 161 \$340.70
5	REAR BUMPER	1		Ry \$853.20
6	REAR BUMPER CLIPS	10	\$5.80	nn \$58.00
7	REAR WINDSCREEN RUBBER	1		nn \$116.00
8	REAR END PANEL UPPER COVERING	1		nn \$207.30
9	REAR END PANEL UPPER COVERING CLIPS	6	\$5.80	nn \$34.80
10	REAR BUMPER SIDE BRACKET RH	1		R \$126.70
11	REAR END PANEL	1		REPAIR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

SUB TOTAL	\$3,665.30
LESS 25%	-\$916.33
PARTS TOTAL	\$2,748.98

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		nn \$80.00
2	REAR WINDSCREEN STOPPER	2	\$15.00	nn \$30.00
3	REAR BUMPER REVERSE SENSOR	1		nn \$350.00
	Acknowledged by Repairer			
	Signature:			
	Date:			
	S/N TOTAL			\$460.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, REFIX & READJUST REAR ACCIDENT AREAS & ETC.

\$600.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL & ETC.

\$800.00

LABOUR CHARGES TO REMOVE, REPLACE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT & ETC. TO EFFECT REPLACE OF REAR TAILGATE.

\$150.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

452 Tagore Industrial Avenue Singapore 787823
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

