



MY CAR CONSULTANT PTE LTD

Reg no.: 2016058782

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date: 10/8/2020
Vehicle: SMH7056Y
Make / Model: HONDA FIT HYBRID
Chassis No: GP5-1336960

Chassis No:		GR 5-1556500		
No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	FRONT BUMPER / JLF	1	\$ 698.00	\$ 698.00
2	FRONT BUMPER SIDE RETAINER / DR	2	\$ 48.20	\$ 96.40
3	FRONT BUMPER SIDE GRILLE RH / DR	1	\$ 167.30	\$ 167.30
4	FRONT BUMPER LOWER GRILLE CENTRE X NAI	1	\$ 212.00	\$ 212.00
5	FRONT BUMPER SPONGE X NAI	1	\$ 198.00	\$ 198.00
6	FRONT GRILLE X NAI	1	\$ 485.00	\$ 485.00
7	FRONT GRILLE CHROME X NAI	1	\$ 198.00	\$ 198.00
8	HEADLAMP RH / DR	1	\$ 987.00	\$ 987.00
9	HEADLAMP LOWER BRACKET RH / RR	1	\$ 112.00	\$ 112.00
				\$ 3,153.70
Less 20%				\$ 630.74
Total				\$ 2,522.96
S/Nett items:				
1	FRONT BUMPER CLIPS SET / NPC	1	\$ 50.00	\$ 50.00
2	FRONT GRILLE CLIPS SET X NAI	1	\$ 50.00	\$ 50.00
				\$ 100.00
Labour to:				
1	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,800.00	\$ 400.00
2	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,600.00	\$ 400.00
3	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
4	REALIGN HEADLAMP	1	\$ 150.00	\$ 150.00
				\$ 1,030.00
		Parts Replacement Amount		\$ 2,622.96
		Total Amount for Labour		\$ 1,030.00
		Total Amount		\$ 3,652.96

Steve (LKK) with ProjL
17/8/20, 4.00pm
3 days
L/S
By AFL spy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: