



MY CAR CONSULTANT PTE LTD

Reg no.: 2016058782

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934
HP: 98888885

Estimation

Date: 10/8/2020

Vehicle: SMH7056Y

Make / Model: HONDA FIT HYBRID

Chassis No: GP5-1336960

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	FRONT BUMPER / <i>DLF</i>	1	\$ 698.00	\$ 698.00
2	FRONT BUMPER SIDE RETAINER / <i>GR</i>	2	\$ 48.20	\$ 96.40
3	FRONT BUMPER SIDE GRILLE RH / <i>GR</i>	1	\$ 167.30	\$ 167.30
4	FRONT BUMPER LOWER GRILLE CENTRE X <i>N/A</i>	1	\$ 212.00	\$ 212.00
5	FRONT BUMPER SPONGE X <i>N/A</i>	1	\$ 198.00	\$ 198.00
6	FRONT GRILLE X <i>N/A</i>	1	\$ 485.00	\$ 485.00
7	FRONT GRILLE CHROME X <i>N/A</i>	1	\$ 198.00	\$ 198.00
8	HEADLAMP RH / <i>GR</i>	1	\$ 987.00	\$ 987.00
9	HEADLAMP LOWER BRACKET RH / <i>GR</i>	1	\$ 112.00	\$ 112.00
				\$ 3,153.70
			Less 20%	\$ 630.74
			Total	\$ 2,522.96
S/Nett items:				
1	FRONT BUMPER CLIPS SET / <i>APC</i>	1	\$ 50.00	\$ 50.00
2	FRONT GRILLE CLIPS SET X <i>N/A</i>	1	\$ 50.00	\$ 50.00
				\$ 100.00
Labour to:				
1	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,800.00	\$ 400.00
2	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,600.00	\$ 400.00
3	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
4	REALIGN HEADLAMP	1	\$ 150.00	\$ 150.00
				\$ 1,030.00
Parts Replacement Amount				\$ 2,622.96
Total Amount for Labour				\$ 1,030.00
Total Amount				\$ 3,652.96

2060.70
-20%
1648.56

30 ✓
x

200
200
30
30

460

Steve (LKK) *WHL*

17/8/20, 4.00pm

3 days

L/S

By AFL spy

P-1648-56

M-30

L-460

2138-56

L/S-1719-84

=1700

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: