

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Aug 2020 Edit Reg		14 Aug 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by adjuster]						
Insured: LOW LILY , ID: S1700499I									
Main Claimant: SBS TRANSIT LTD									
Vehicle Reg. No.: SBS6051P		Date of Loss: 07/08/2020 00:00 - :59 [108 Months and 30 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 8473204268SG		Policy/Cover Note No.: 1900165285 (Comprehensive)							
Vehicle Reg. No. (Insured): SMN3100Y		Policy No. (Claimant):							
		Excess:							
Repairer: Sbs Transit Ltd (Bedok) (HQ) 1470 BEDOK NORTH AVE 4, 489946 Bedok - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Yong, Joanne] Joanne-LF.yong@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 26/08/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SBS6051P (8473204268SG)**
[SMN3100Y]
TP
SBS TRANSIT LTD
Aug 7 2020 12:00AM
[LOW LILY]
Sbs Transit Ltd (Bedok)

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	18/08/20 16:57	Video - Accident	Load MP4	
2	18/08/20 16:57	Video - Accident	Load MP4	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/09/20 12:26	General View	Load JPG	☒
2	03/09/20 12:26	General View	Load JPG	☒
3	03/09/20 12:26	General View	Load JPG	☒
4	03/09/20 12:26	General View	Load JPG	☒
5	03/09/20 12:26	General View	Load JPG	☒
6	03/09/20 12:26	General View	Load JPG	☒
7	03/09/20 12:26	General View	Load JPG	☒
8	03/09/20 12:26	General View	Load JPG	☒
9	03/09/20 12:26	General View	Load JPG	☒
10	03/09/20 12:26	General View	Load JPG	☒
11	03/09/20 12:26	General View	Load JPG	☒
12	03/09/20 12:26	General View	Load JPG	☒
13	03/09/20 12:26	General View	Load JPG	☒
14	03/09/20 12:26	General View	Load JPG	☒
15	03/09/20 12:26	General View	Load JPG	☒
16	03/09/20 12:26	General View	Load JPG	☒
17	03/09/20 12:26	General View	Load JPG	☒
18	03/09/20 12:26	General View	Load JPG	☒
19	03/09/20 12:26	General View	Load JPG	☒
20	03/09/20 12:26	General View	Load JPG	☒
21	03/09/20 12:26	Chassis Number	Load JPG	☒
22	03/09/20 12:26	Odometer Reading	Load JPG	☒
23	03/09/20 12:30	General View	Load JPG	☒
24	03/09/20 12:30	General View	Load JPG	☒
25	03/09/20 12:30	General View	Load JPG	☒
26	03/09/20 12:30	General View	Load JPG	☒
27	03/09/20 12:30	General View	Load JPG	☒
28	03/09/20 12:30	General View	Load JPG	☒
29	03/09/20 12:30	General View	Load JPG	☒
30	03/09/20 12:30	General View	Load JPG	☒
31	03/09/20 12:30	General View	Load JPG	☒
32	03/09/20 12:30	General View	Load JPG	☒
33	03/09/20 12:30	General View	Load JPG	☒
34	03/09/20 12:30	General View	Load JPG	☒
35	03/09/20 12:30	General View	Load JPG	☒
36	03/09/20 12:30	General View	Load JPG	☒

Video				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
37	03/09/20 12:30	General View		Load JPG	☒
38	03/09/20 12:30	General View		Load JPG	☒
39	03/09/20 12:30	General View		Load JPG	☒
40	03/09/20 12:30	General View		Load JPG	☒
41	03/09/20 12:30	General View		Load JPG	☒
42	03/09/20 12:30	General View		Load JPG	☒
43	03/09/20 12:30	General View		Load JPG	☒
44	03/09/20 12:30	General View		Load JPG	☒
45	03/09/20 12:31	Reinspection Photo		Load JPG	☒
46	03/09/20 12:31	Reinspection Photo		Load JPG	☒
47	03/09/20 12:31	Reinspection Photo		Load JPG	☒
48	03/09/20 12:31	Reinspection Photo		Load JPG	☒
49	03/09/20 12:31	Reinspection Photo		Load JPG	☒
50	03/09/20 12:31	Reinspection Photo		Load JPG	☒
51	03/09/20 12:31	Reinspection Photo		Load JPG	☒
52	03/09/20 12:31	Reinspection Photo		Load JPG	☒
53	03/09/20 12:31	Reinspection Photo		Load JPG	☒
54	03/09/20 12:31	Replacement Part Photo		Load JPG	☒
55	03/09/20 12:31	Replacement Part Photo		Load JPG	☒
56	03/09/20 12:31	Replacement Part Photo		Load JPG	☒
57	03/09/20 12:31	Replacement Part Photo		Load JPG	☒
58	03/09/20 12:31	Replacement Part Photo		Load JPG	☒
59	03/09/20 12:31	Replacement Part Photo		Load JPG	☒
60	03/09/20 12:31	Replacement Part Photo		Load JPG	☒
61	03/09/20 12:31	Replacement Part Photo		Load JPG	☒
62	03/09/20 12:31	Replacement Part Photo		Load JPG	☒
63	03/09/20 12:31	Replacement Part Photo		Load JPG	☒
64	03/09/20 12:31	After Repair Photo		Load JPG	☒
65	03/09/20 12:31	After Repair Photo		Load JPG	☒
66	03/09/20 12:31	After Repair Photo		Load JPG	☒
67	03/09/20 12:31	After Repair Photo		Load JPG	☒
68	03/09/20 12:31	After Repair Photo		Load JPG	☒
69	03/09/20 12:31	After Repair Photo		Load JPG	☒

Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/08/20 12:06	TP Singapore Accident Statement		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	18/08/20 16:56	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG20008519/T1TF3S2**Date:** 09/09/2020**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900165285
Claimant Vehicle No :	SBS6051P	Insured Vehicle No :	SMN3100Y
Date of Loss:	07/08/2020	Nature of Claim:	TP
		Claim No:	8473204268SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBS6051P	Engine No:	90292609015659
Make & Model:	MERCEDES-BENZ CITARO O530, 6.4 D (A)	Chassis No:	WEB62808323121931
Reg. Date:	08/07/2011 (Man. Year: 2011)	Odometer:	822217 km
Colour:	Multi-colour		
Engine Capacity:	6374 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8/8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	14/08/2020	
Date Inspected:	17/08/2020	Inspected At: Sbs Transit Ltd (Bedok) (HQ) 1470 BEDOK NORTH AVE 4 Singapore 489946
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT CORNER BUMPER LH	Cracked	0.00 F	*- F
2	1		*FRONT SIDE LAMP LH	Cracked	0.00 F	*- F
3	1		*FRONT HEADLAMP LH	Cracked	0.00 F	*- F
4	1		*FRONT SIDE WINDSCREEN GLASS LH	Cracked	0.00 F	*- F
5	1		*FRONT WINDSCREEN GLASS SEALANT	Necessary	0.00 F	*- F
6	1		*FRONT DOOR LH RUBBER	Torn	0.00 F	*- F
F=Franchise part.						
				Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >