

SJE : _____
Date of Survey : _____
Date of ReSurvey : _____
Contacts : _____

Vehicle Nos : **SMD 90 P**
Model : **BMW 520i**
Year : _____
Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: 2013

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Bootlid	1	\$ 1,488.90	\$ 1,488.90	BTv
2	Bootlid logo	1	\$ 106.00	\$ 59.00 106.00	NEC
4	Bootlid inner trim board	1	\$ 179.70	\$ 179.70	NDX
5	Bootlid lock mechanism	1	\$ 345.60	\$ 345.60	NDX
6	Bootlid lock striker	1	\$ 84.10	\$ 84.10	NDX
7	Bootlid lock switch	1	\$ 298.50	\$ 298.50	NDX
8	Bootlid hinge	2	\$ 154.80	\$ 309.60	NDX
10	Bootlid lamp	2	\$ 318.90 486.90	\$ 637.80 973.80	CUTV
11	Bootlid weatherstrip	1	\$ 188.50	\$ 188.50	NDX
12	Bootlid no plate lamp	2	\$ 56.20	\$ 112.40	NDX
13	Rear bumper	1	\$ 1,858.00	\$ 1,563.35 1,858.00	BRV
14	Rear bumper lower	1	\$ 385.60	\$ 310.00 385.60	BRV
15	Rear bumper reinforcement	1	\$ 791.50	\$ 691.00 791.50	BRV
16	Rear bumper reinforcement bracket	2	\$ 152.00	\$ 304.00	NSX
17	Rear bumper side retainer	2	\$ 155.90 105.60	\$ 311.80 371.20	NEC
18	Rear bumper bracket	2	\$ 115.00	\$ 230.00	BRV
19	Rear bumper reflector	2	\$ 75.00 150.00	\$ 150.00 316.00	BRV
20	Rear bumper tow cap	1	\$ 65.30	\$ 28.95 65.30	MIS
21	Rear bumper centre beam	1	\$ 383.00	\$ 383.00	BRV
22	Rear bumper lower centre cover	1	\$ 456.00	\$ 310.00 456.00	BRV
23	Rear bumper reverse sensor	4	\$ 255.40 388.00	\$ 1,021.60 1,552.00	SCV
24	Rear end panel	1	\$ 982.20	\$ 885.00 982.20	DDV
25	Rear end panel top garnish	1	\$ 187.40	\$ 187.40	BRV
26	Spare tyre panel	1	\$ 1,998.70	\$ 1,998.70	NDX
27	Spare tyre panel inner trim	1	\$ 125.50	\$ 125.50	ND
28	Spare tyre panel insulator	1	\$ 300.00	\$ 300.00	X
29	Spare tyre panel inner sponge	1	\$ 70.80	\$ 70.80	
30	Head restraint system	2	\$ 666.40 2,500.00	\$ 1,333.20 5,000.00	Acty, old
31	Head restraint system control unit	1	\$ 2,280.00	\$ 1,262.74 2,280.00	NEC
36	Tail lamp	2	\$ 690.00 1,069.20	\$ 690.00 2,138.40	BRV
			Parts Sub Total :	\$ 23,762.70	
			5% Discount	\$ 1,188.14	
			PARTS TOTAL :	\$ 22,574.57	

@ 5%
11,470.04
573.50
10896.54

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00 <i>NNX</i>
2	Bootlid sealant	1	\$ 100.00	\$ 100.00 <i>NNX</i>
3	Bootlid inner trim board clips	1	\$ 50.00	\$ 50.00 <i>NNX</i>
4	Bootlid lamp clips	2	\$ 50.00	\$ 100.00 <i>NSX</i>
5	Bootlid lamp seal	2	\$ 60.00	\$ 120.00 <i>NEC</i>
6	Bootlid emblem 'F10 SINGAPORE'	1	\$ 60.00	\$ 60.00 <i>NEC</i>
7	Bootlid reverse camera	1	\$ 480.00	\$ 480.00 <i>NDX</i>
8	Rear bumper clips	1	\$ 50.00	\$ 50.00 <i>NEC</i>
9	Rear bumper lower clips	1	\$ 50.00	\$ 50.00 <i>NEC</i>
10	Rear bumper lower centre cover clips	1	\$ 50.00	\$ 50.00 <i>NEC</i>
11	Rear bumper reverse sensor seal	2	\$ 68.00	\$ 272.00 <i>NEC</i>
12	Rear end panel sealant	1	\$ 100.00	\$ 100.00 <i>NEC</i>
13	Rear end panel top garnish clips	1	\$ 50.00	\$ 50.00 <i>NEC</i>
14	Rear no plate with casing	1	\$ 80.00	\$ 80.00 <i>NDX</i>
15	Tail lamp seal	2	\$ 100.00	\$ 200.00 <i>NNX</i>
16	Tail lamp clips	2	\$ 50.00	\$ 100.00 <i>NSX</i>
17	Rear twin exhaust muffler tip	2	\$ 113.60	\$ 227.20 <i>NDX</i>

SPECIAL NETT TOTAL : \$ 602.00 2,169.20

Nos.	LABOUR	S\$
1	R&R bootlid component	\$ 60.00 100.00 ✓
2	R&R reverse sensor	\$ 60.00 60.00 ✓
3	R&R exhaust muffler complete assy	\$ 150.00 <i>NNX</i>
4	R&R head restraint	\$ 200.00 350.00 ✓
5	Reset head restraint system control unit	\$ 300.00 500.00 ✓
6	Spray reverse sensor (4 pcs)	\$ 40.00 40.00 ✓
7	Upholstery	\$ 300.00 <i>NNX</i>
8	Check wiring	\$ 30.00 30.00 ✓
9	Diagnostic reset fault code	\$ 150.00 300.00 ✓
10	Panel beat	\$ 100.00 1,600.00 ✓
11	Rust proofing	\$ 60.00 60.00 ✓
12	Spray painting	\$ 800.00 1,600.00 ✓

LABOUR TOTAL : \$ 2,700.00 5,340.00

PARTS TOTAL : \$ 22,574.57
SPECIAL NETT TOTAL : \$ 2,169.20
LABOUR TOTAL : \$ 5,340.00

GRAND TOTAL : \$ 30,083.77

PARTS 10,896.54
S/N 602.00
LABOUR 2,700.00

14,198.54
2,839.71
11,358.83

L/S 11,300/2

Survey 1400hrs Resurvey 1330hrs
Tim Lin Tim Lin
17/8/2020 18/8/2020

Lamp sum repair
Repair days 7

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: