

Car Number: SLB7434H
 Model : KIA Forte K3 1.6
 Damaged Area: (Front RH Side Portion)
 Repairer Estimation Cost of Repair :
 Supplementary may be included during the cost of repair :

Not Authorized
 Name
 17/8/20
 d/s \$8500/
 8 days.

Parts / Material :

- 1 Front Bumper
- 2 Front Bumper Fog Lamp RH
- 3 Front Bumper *Sponge*
- 4 Front Bumper Fog Lamp Garnish RH
- 5 Front Bumper Lower Centre Grille
- 6 Front Bumper Reinforcement
- 7 Front Bumper Retainer RH
- 8 Front *wiper washer tank*
- 9 Front *wiper washer tank motor*
- 10 Front Bumper Number Plate Garnish
- 11 Front Bumper Logo
- 12 Front Bumper Clips (Set)
- 13 Front Fender RH
- 14 Front Fender Inner Shield RH
- 15 Front Fender Inner Shield Clips (Set)
- 16 Front Fender Bracket RH
- 17 Front Wheel House Inner Panel RH
- 18 Front Door RH
- 19 Front Door Hinges @ 37.50
- 20 Front Headlamp RH LED/HID *1523*
- 21 Front Radiator Grille Assy
- 22 Front Radiator Grille Top Garnish
- 23 Front Radiator Grille Clips (Set)
- 24 Front Bonnet
- 25 Front Bonnet Rubber
- 26 Front Bonnet Insulator
- 27 Front Bonnet Insulator Clips (Set)
- 28 Front Bonnet Lock
- 29 Front Support Panel
- 30 AC Condenser
- 31 Front Suspension RH
- 32 Front Lower Arm RH
- 33 Front Knuckle Arm
- 34 Front Hub Bearing Assy RH
- 35 Front *Dr. Shaft* RH

D.S	\$	745.20	—
SRO	\$	255.20	—
Torn	\$	121.60	✓
D.S	\$	175.80	—
D.S	\$	214.20	—
Surf	\$	375.40	—
CN	\$	78.00	—
D.S	\$	62.00	—
D.S	\$	290.00	—
shutted	\$	112.60	—
RR	\$	104.20	—
RR	\$	60.00	—
D.S	\$	786.50	—
Torn	\$	215.30	—
RR	\$	60.00	—
D.S	\$	145.60	—
RR		Repair	✓
RR		Repair	✓
RR	\$	75.00	X
SRO	\$	2,698.00	—
CNA	\$	295.30	—
RR	\$	175.40	X
RR	\$	60.00	X
RR/Surf	\$	970.50	—
RR	\$	62.40	—
RR	\$	275.60	X
RR	\$	60.00	X
Torn	\$	214.20	—
D.S	\$	985.40	—
RR	\$	1,246.30	X
RR	\$	468.50	—
RR	\$	485.50	—
RR	\$	596.50	X
Damage	\$	199.50	—
RR	\$	1,256.00	X

Parts : \$ 13,925.70
 Less Parts 10% : \$ 1,392.57
Total Parts : \$ 12,533.13

900590
 10%
 \$105.31

Special Net Items :

- Front Number Plate W/Garnish
 Front Bumper Angle Sensor

RR	\$	80.00	X
RR	\$	320.00	X

Front Rim RH
Front Tyre RH
Radiator Coolant

11	\$	750.00	X
11	\$	450.00	X
11	\$	80.00	30
Total S/N Parts :		\$	1,680.00

Labour :

To Remove, Repair & Renew Affected Accident Areas	\$	1,400.00	1000
To Putty, Spray Paint on Affected Accident Areas	\$	1,200.00	1100
To Check & Re-Connect all electrical wiring	\$	50.00	30
To Remove, Install & Conduct Radiator Pressure Leakage Test	\$	200.00	
To Remove, Install AC Condenser & Top Up Gas	\$	200.00	100
To Conduct Wheel Alignment	\$	200.00	60
To Renew, Balance & Replace Front RH Tyre	\$	80.00	X
To <i>disassemble & replace front under carriage</i>	\$	450.00	120
To Re-position Front Sensor & Angle Sensor	\$	200.00	X
To Rust Proof Affected Areas	\$	150.00	80
Total Labour :		\$	4,130.00

TOTAL PARTS : \$ 12,533.13
TOTAL SPECIAL NET ITEM : \$ 1,680.00
TOTAL LABOUR : \$ 4,130.00
TOTAL REPAIR COST : \$ 18,343.13

DATE OF SURVEY / INSPECTED:
RECOMMENDED PART BY PART / LUMP SUM :
RECOMMENDED NUMBER OF DAYS :
SURVEY BY / SURVEYOR FIRM :
RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :
FINALISED AMOUNT :

9 - 8105.31
S.N. - 30.00
2 - 2490
10625.31

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: