

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20008526/UPS3Q2
Date: 12/05/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549
Claimant Vehicle No :	SJJ7376Z	Insured Vehicle No :	GBG8486T
Date of Loss:	14/08/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0001529

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ7376Z		
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Engine No:	1NZX800522
Reg. Date:	24/09/2008 (Man. Year: 2008)	Chassis No:	MR053HY9305080388
Colour:	Black	Odometer:	239712 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,407.75	914.54	6,493.21	87.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,150.00	1,020.00	2,130.00	67.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,557.75	1,934.54	8,623.21	81.68
Approved Total (Overridden) (S\$)		1,500.00		

Nett Amount (S\$)	10,557.75	1,500.00	9,057.75	85.79
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 17/08/2020

Date Inspected: 17/08/2020

Estimated Period of Repair: 3.0 days

Inspected At: Asia Motorsports Solution Pte Ltd (HQ)
37A Everitt
Singapore 428586

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 May 2021)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJJ7376Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	981.00 FL	*366.05 FL
2	2		*REAR BUMPER SIDE RETAINER (LONG)	Not Necessary	130.50 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER (SHORT)	Not Necessary	112.00 FL	*- FL
4	2		*REAR BUMPER REFLECTORS	Not Necessary	196.40 FL	*- FL
5	2		*REAR BUMPER REFLECTORS CHROME COVER	Not fitted	244.00 FL	*- FL
6	1		*REAR BOOTLID	Repair	979.50 FL	*- FL
7	2		*REAR BOOTLID HINGES (NPA)	Not Necessary	0.00 FL	*- FL
8	1		*REAR BOOT EDGE WEATHERSTRIP	Not Necessary	264.00 FL	*- FL
9	1		*REAR BOOTLID INNER LOCK	Not Necessary	238.00 FL	*- FL
10	1		*REAR BOOTLID INNER LOCK COVER	Not Necessary	98.00 FL	*- FL
11	1		*REAR BOOTLID LOCK CATCH	Not Necessary	72.00 FL	*- FL
12	1		*REAR BOOTLID TOYOTA BADGE	Not Necessary	62.00 FL	*- FL
13	1		*REAR BOOTLID VIOS EMBLEM	Not Necessary	72.00 FL	*- FL
14	1		*REAR BOOTLID E EMBLEM	Not Necessary	48.00 FL	*- FL
15	2		*REAR BOOTLID RUBBER STOPPER	Not Necessary	64.80 FL	*- FL
16	1		*REAR BOOTLID CENTRE MOULDING	Not Necessary	278.00 FL	*- FL
17	2		*RHS & LHS TAILLAMPS	Not Necessary	1,344.80 FL	*- FL
18	1		*REAR SPARE TYRE PANEL TOP BOARD	Not Necessary	172.00 FL	*- FL
19	1		*REAR SPARE TYRE PANEL TOP BOARD COVER MAT	Not Necessary	98.00 FL	*- FL
20	2		*RHS & LHS CORNER TOOL TRAYS	Not Necessary	224.00 FL	*- FL
21	1		*REAR EXHAUST SILENCER ASSEMBLY	Not Necessary	682.00 FL	*- FL
22	2		*REAR EXHAUST SILENCER ASSEMBLY MOUNTING	Not Necessary	98.00 FL	*- FL
23	1		*REAR END PANEL	Repair	978.00 FL	*- FL
24	2		*REAR END PANEL OUTER BRACKETS	Not Necessary	98.00 FL	*- FL
25	1		*REAR END PANEL TOP GARNISH	Not Necessary	242.00 FL	*- FL
26	1		*REVERSE SENSOR	Serviceable	280.00 FS	*- FS
27	1		*REAR LICENCE PLATE W/BASE	Not Necessary	75.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	2		*REAR LICENCE PLATE LAMPS (NPA)	Not Necessary	0.00 FS	*- FS
29	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
30	1		*REAR BUMPER LOWER DIFFUSER (BODY KIT)	Deformed / Cracked	980.00 FS	*600.00 FS
31	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*40.00 FS
32	1		*REAR BOOTLID TOP SPOILER (NPA)	Not Necessary	0.00 FS	*- FS
33	1		*REAR BOOTLID TOP SPOILER SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,352.00	1,006.05
- List Item Discount on L Items 25.00/25.00% (\$)	1,944.25	91.51
Total Parts (\$)	7,407.75	914.54

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,400.00	300.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED AND REPAIRED AREAS	New	1,000.00	600.00
3	TO REMOVE AND REFIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTION	New	150.00	20.00
4	TO REMOVE REAR FITTINGS ,GARNISH ,TRIMMINGS ETC SO AS TO FACILITATE REPAIRS AT REAR	New	150.00	60.00
5	TO REMOVE AND REPLACE REAR EXHAUST SILENCER ,REALIGN TO FIT AND CHECK FOR PROPER SYSTEM FUNCTION	New	200.00	0.00
6	TO REMOVE AND REPLACE REVERSE SENSORS AND CHECK FOR PROPER FUNCTION	New	100.00	40.00
7	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	150.00	0.00
Gross Labour Cost (S\$)			3,150.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >