

Spark Car Care
ComfortDelgro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax:62815767

Finalization Form

Bil : Great American Ins **Vehicle Number** : SMS2820H
Attn to : LKK Guo Qiang **Type Of Claim** : TP

A. Spare parts \$ <u>749.50</u> B. Supplementary \$ <u>3,061.00</u> C. Nett Price \$ <u>-</u> D. Supp Nett Price \$ <u>-</u> E. S/Nett \$ <u>-</u>	F. Total Parts \$ <u>3,048.40</u> G. Total Labour \$ <u>560.00</u> H. Total Repair \$ <u>3,608.40</u> I. Excess <u>\$6,057.20</u> P/P Total <u>3,608.40</u>
---	--

Total Spare Parts Price	\$ 3,810.50	✓
Cost plus / List Down <u>20%</u>	762.10	
Total	3,048.40	✓

Total Nett Price	\$ -	
Nett Price Less _____	\$ -	
Total	-	

Lump Sum Less _____ \$ -

Lump Sum Rounding _____

Total Finalized _____

N.B. If we DO NOT receive your reply within 2 weeks, we shall treat the above finalized amount as confirmed & correct.

Remarks : Please confirm and revert by Fax or Email

Date In : _____	Total Repair Day : _____
Date Survey : _____	LOU/ Day : _____
Date Out : _____	Total LOU : _____
Sat/Sun/Ph. : _____	Rental/Day : _____
Authorized Repair Day : <u>4</u>	Total Rental : _____

Submitted By / Date :

Andrew 24/05/20

Confirmed By / Date :

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : SMS2820H Case Owner : PATRICK

Make & Model : HYUNDAI IONIQHYBRID Year Manufacture : 2020

Chassis No : KMHC851CVLU201011 Engine No : L13A4054292

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	FRONT BUMPER / <i>le</i>	1	—	\$ 430.00			
2	FRONT BUMPER LH SIDE RETAINER / <i>le</i>	1	—	\$ 28.00			
3	FRONT BUMPER RH SIDE RETAINER <i>xnn</i>	1		\$ 28.00			
4	FRONT BUMPER TOP FRAME(SILVER) / <i>at</i>	1	—	\$ 108.50			
5	FRONT LH BUMPER LED LAMP COVER / <i>at</i>	1	—	\$ 165.00			
6	FRONT BUMPER CLIP / <i>mfc</i>	6	—	\$ 18.00			
7	0	1					
8	0 <i>Headlamp LH</i> ✓ BR	1	—	\$ 2111.00			
9	0 <i>front support panel</i> ✓ CRA	1	—	\$ 950.00			
10	0	1					
11	0	1					
12	0	1					
13	0	1					
14	0	1					
15	0	1					
16	0	1					
17	0	1					
18	0	1					
19	0	1					
20	0	1					
21	0	1					
22	0	1					
23	0	1					
24	0	2					
25	0	1					
26	0	1					
27	0	1					
28	0	1					
29	0	1					
30	0	1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax: 62815767

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : SMS2820HMake & Model : HYUNDAI IONIQHYBRIDYear of Manufacture : 2020Chassis No. : KMHC851CVLU201011

Engine No. : _____

Policy No. : _____

Time of Accident : _____

Ins Company : TM / GREAT AMERICAN

Excess : _____

Date of Accident : 7-Aug-20

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimates**Case Owner : PATRICK

Signature : _____

Parts (a) Cost / List Price Items \$ 777.50Plus/Less 20% \$ 155.50Total of Cost / List \$ 622.00(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -Total Parts Cost (Appendix A) \$ 622.00Labour (Appendix B) \$ 2,040.00Total Repair Cost \$ 2,662.00

Contact No

Frt Counter Operation

63837103 - Patrick Tia

PatrickTia@sparkcarcare.com

63837730 - Brenda Ng

BrendaNg@sparkcarcare.com

63837466 - Rohani

RohaniM@sparkcarcare.com**Workshop Operation**

63837656 - Ngo Toh Wee

Ngotw@sparkcarcare.com

63838115 - William Wang

WilliamWangKS@sparkcarcare.com

63837362 - Andrew Goh

AndrewCorneliusGoh@sparkcarcare.com

The above total will be subjected to 7% G.S.T.

*Guo Qiang @ lkk auto. com.*Name of Surveyor : Guo Qiang -82880282Company : LKKSurvey conducted on : 17/8/2020 at _____**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 7 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____