

**Spare Parts**

Vehicle No : SMS2820H Case Owner : PATRICK  
 Make & Model : HYUNDAI IONIQHYBRID Year Manufacture : 2020  
 Chassis No : KMHC851CVLU201011 Engine No : L13A4054292  
 Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_  
 Order By : \_\_\_\_\_ Type of Claim : TP

| S/No | Part Description                    | QTY | Cost Price | List Price | Nett Price | S/N | Disposition By Surveyor |
|------|-------------------------------------|-----|------------|------------|------------|-----|-------------------------|
| 1    | FRONT BUMPER / ll                   | 1   | -          | \$ 430.00  |            |     |                         |
| 2    | FRONT BUMPER LH SIDE RETAINER / ll  | 1   | -          | \$ 28.00   |            |     |                         |
| 3    | FRONT BUMPER RH SIDE RETAINER x an  | 1   |            | \$ 28.00   |            |     |                         |
| 4    | FRONT BUMPER TOP FRAME(SILVER) / at | 1   | -          | \$ 108.50  |            |     |                         |
| 5    | FRONT LH BUMPER LED LAMP COVER / at | 1   | -          | \$ 165.00  |            |     |                         |
| 6    | FRONT BUMPER CLIP / MGL             | 6   | -          | \$ 18.00   |            |     |                         |
| 7    | 0                                   | 1   |            |            |            |     |                         |
| 8    | 0 Headlamp LH ✓ BR                  | 1   | -          | \$ 2111.00 | (A)        |     |                         |
| 9    | 0 Front support panel ✓ CRA         | 1   | -          | \$ 950.00  | (A)        |     |                         |
| 10   | 0                                   | 1   |            |            |            |     |                         |
| 11   | 0                                   | 1   |            |            |            |     |                         |
| 12   | 0                                   | 1   |            |            |            |     |                         |
| 13   | 0                                   | 1   |            |            |            |     |                         |
| 14   | 0                                   | 1   |            |            |            |     |                         |
| 15   | 0                                   | 1   |            |            |            |     |                         |
| 16   | 0                                   | 1   |            |            |            |     |                         |
| 17   | 0                                   | 1   |            |            |            |     |                         |
| 18   | 0                                   | 1   |            |            |            |     |                         |
| 19   | 0                                   | 1   |            |            |            |     |                         |
| 20   | 0                                   | 1   |            |            |            |     |                         |
| 21   | 0                                   | 1   |            |            |            |     |                         |
| 22   | 0                                   | 1   |            |            |            |     |                         |
| 23   | 0                                   | 1   |            |            |            |     |                         |
| 24   | 0                                   | 2   |            |            |            |     |                         |
| 25   | 0                                   | 1   |            |            |            |     |                         |
| 26   | 0                                   | 1   |            |            |            |     |                         |
| 27   | 0                                   | 1   |            |            |            |     |                         |
| 28   | 0                                   | 1   |            |            |            |     |                         |
| 29   | 0                                   | 1   |            |            |            |     |                         |
| 30   | 0                                   | 1   |            |            |            |     |                         |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.