



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

INS : THAI SING FOODSTUFFS INDUSTRY PTE LTD
42 WOODLANDS TERRACE, S
SINGAPORE 738457

TEL : 6755 2166

FAX :

ATTN :

OUR REF NO : XD2753S

CLAIM TYPE : THIRD PARTY

P INS. CO. : ALLIED WORLD ASSURANCE COMPANY LTD

ACCIDENT DATE : 06/08/2020

P VEH REG NO : XD2753S

ESTIMATE

NO : QUOT202008-000025(00)

DATE : 14/08/2020

POLICY NO : 2100335538-07

VEH REG NO : GBC6022H

MAKE/MODEL : NISSAN URVAN 3.0 5MT ABS
AB 5DR LWB PANEL

CHASSIS NO : JN1MG4E25Z0796846

ENGINE NO : ZD30297310K

REG. DATE : 2013

Estimate Repair Cost to Vehicle No : GBC6022H

Description	Quantity	Unit Price	Amount
		S\$	S\$
LIST PRICE			
1 Tailgate	1	1,998.30	1,998.30
2 Tailgate weathertrip	1	190.30	190.30
3 Tailgate center logo	1	75.70	75.70
4 Tailgate 'URVAN' sticker	1	38.10	38.10
5 Tailgate inner lock	1	389.90	389.90
6 Tailgate inner lock cover	1	76.80	76.80
7 Tailgate actuator assy	1	184.80	184.80
8 Tailgate lock striker	1	65.70	65.70
9 Tailgate center garnish	1	486.30	486.30
10 Tailgate inner trimboard	1	175.10	175.10
11 Tailgate inner trimboard clips	20	8.00	160.00
12 Taillamp assy - LH	1	267.30	267.30
Rear end panel	1	764.20	764.20
Rear bumper	1	734.00	734.00
Rear bumper center bracket	1	189.10	189.10
Rear bumper side retainer - LH/RH	2	38.60	77.20
Rear bumper sensor	2	294.00	588.00
Rear bumper clips	15	8.00	120.00
Rear wiper arm	1	85.60	85.60
Rear wiper blade	1	45.20	45.20
Rear wiper cap	1	18.80	18.80
			6,730.40
		Less 30%	2,019.12
			4,711.28
SPECIAL NET			
Rear number plate	1	40.00	40.00
Okm/h sticker	1	25.00	25.00
Rear windscreen sealant	1	60.00	60.00
			125.00
ABOUT			
remove and refix rear windscreen glass	1	150.00	150.00
remove and refix rear bumper sensor	1	100.00	100.00
transfer damaged tailgate interior mechanism to new tailgate	1	120.00	120.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before repair spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : THAI SING FOODSTUFFS INDUSTRY PTE LTD
42 WOODLANDS TERRACE, S
SINGAPORE 738457

TEL : 6755 2166

FAX :

ATTN :

YOUR REF NO : XD2753S

CLAIM TYPE : THIRD PARTY

TP INS. CO. : ALLIED WORLD ASSURANCE COMPANY LTD

ACCIDENT DATE : 06/08/2020

TP VEH REG NO : XD2753S

ESTIMATE

NO : QUOT202008-000025(00)

DATE : 14/08/2020

POLICY NO : 2100335538-07

VEH REG NO : GBC6022H

MAKE/MODEL : NISSAN URVAN 3.0 5MT ABS
AB 5DR LWB PANEL

CHASSIS NO : JN1MG4E25Z0796846

ENGINE NO : ZD30297310K


REG. DATE : 2013

Estimate Repair Cost to Vehicle No : GBC6022H

Description	Quantity	Unit Price	Amount
		S\$	S\$
28 To check and rectify wiring system	1	80.00	80.00
29 To panel beat and straighten rear chassis frame, rear floorboard panel, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
30 To putty and spray same on affected areas	1	800.00	800.00
31 To supply and paste artwork on tailgate	1	180.00	180.00
			2,430.00
		TOTAL	S\$ 7,266.28
		ADD GST @ 7%	508.64
		GRAND TOTAL	S\$ 7,774.92

SINGAPORE DOLLAR SEVEN THOUSAND SEVEN HUNDRED SEVENTY-FOUR AND CENTS NINETY-TWO ONLY

FOR TONG LUCK AUTO PTE LTD


AUTHORISED SIGNATURE