nneth	2000.8535/Kqf3
From:	SSIGNMENT
Estimated Cost:	Veh No: GBC 603211 Yr Regn: 04, 13
· · · · · · · · · · · · · · · · · · ·	Type: M.Car / M.Cycle / Bus Wan Lorry / Taxl / Prime Mover /
OD TP/WS/TP RES/OD RES/EVA/INV/MV To Inspect Vehicle No:	Truck / Trailer or
MAN	Make: NIS Urvan c.c 293
of Tony Link	Colour White AC: Insured / Std / NI / NA
Insured:	Sp.Reading 307761 T/Radio: Insured / Std / NI / NA
Policy No. BVFCSB0006702015	Eng/No:
Claims No. NSV2000225/PC	_ CNO: JNIMG4 & 25.707968
Sum laws d	Gen. Cond: 800d / Fair / Poor / Burnt
(Client's Record)	Steering: Inother / Jammed / Leaked / Burnt or
Make of Veh:	Brake: Ingfder / Jammed / Leaked J Burnt or
	Modi: Nil) S/Rim / STD A/Rim or
(Policy Condition)	Tyre Size: F: 193R1518
Remark: The veh had commenced its N/S O/S	R:
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI / TOYO / YOKO or
Bal. or Market Value:	- Freed
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs: O3 days Res.: Yes or No	D.O.A. 6/8/120 D.O.I. 17/8/20
Lum Sum: 20 % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear I O/S / N/S / U/C / Rooftop or
Date:Person Contacted: Vehicle: IN / OUT	
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
Kenneth confirmed LS \$3900, 5 c	lays (Red \$3366.28, 46%)
Onto/Time, File Pass to? : Prell. Report	Days Of Repair: 5
11/00 Typiot	
Outa/Time, File Return to?	Survey Fee:
Add Fee:	
	Interview (\$) Funds
Panart Farmat	
Report Format: TP Lump Sum / I.B.I: (\$ 3900	Tech Invs (\$) Others



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : THAI SING FOODSTUFFS INDUSTRY PTE LTD

42 WOODLANDS TERRACE, S

SINGAPORE 738457

Not Nothoriki POLICY NO

ESTIMATE NO

: QUOT202008-000025(00)

DATE

: 14/08/2020

: 2100335538-07

VEH REG NO : GBC6022H

MAKE/MODEL : NISSAN URVAN 3.0 5MT ABS AB 5DR LWB PANEL

CHASSIS NO : JN1MG4E25Z0796846

: ZD30297310K

ENGINE NO

: 2013

CLAIM TYPE TP INS. CO.

YOUR REF NO

TEL : 6755 2166

ATTN:

: XD2753S

: THIRD PARTY

: ALLIED WORLD ASSURANCE COMPANY LTD

REG. DATE

ACCIDENT DATE : 06/08/2020

TP VEH REG NO : XD2753S

Estimate Repair Cost to Vehicle No: GBC6022H

	<u> </u>	tillate (topus	Quantity	Unit Price	Amount
	Description		Quantity	<u>S\$</u>	<u>s\$</u>
					1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	LIST PRICE		1	A 1,998.30	
1			1	190.30	190.30 X
2	A STATE OF THE STA		1	Ma 75.70	75.70
3			1	Ma 38.10	38.10
4	Tailgate 'URVAN' sticker		1	389.90	Net 389.90 -
5			. 1	76.80	nu 76.80 -
6	_		1	184.80	184.80 7
7	Tailgate actuator assy		1	65.70	← 65.70 X
8	Tailgate lock striker		1	486.30	486.30 7
9	Tailgate center garnish		1	175.10	\$ 175.10 X
10	Tailgate inner trimbooard		20	8.00	Mc 160.00
11	Tailgate inner trimbooard	clips	1,000	267.30	CM 267.30 -
12	Taillamp assy - LH		1	764.20	By 764.20 —
13	Rear end panel		1		Bu 734.00 -
14	Rear bumper		1	734.00	189.10
15	Rear bumper center brack		1	189.10	S 77.20 X
16	Rear bumper side retaine	- LH/RH	2	38.60	11.20
17	Rear bumper sensor	LKK Auto Consultants hence notify	2	294.00	Nd 588.00 20012
18	Rear bumper clips	the Repairer of the following:	15	8.00	Me 120.00 5012
19	Rear wiper arm	To resurvey before/after spray painting To display damaged part(s) during resurvey To display damaged part(s) during resurvey	1	85.60	By 85.60 -
20	Rear wiper blade	Parts prices are subject to confirmation	1	45.20	In 45.20 X
21	Rear wiper cap	 Third party survey is on a "Without Prejudice" basis 	1	18.80	mir 18.80 -
		No illegal modification(s) is allowed			6,730.40
		 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company 		Less 30%	2,019.12
			1		4,711.28
	SPECIAL NET	Acknowledged by Repairer Signature:	1		Sa 40.00 X
22	Rear number plate	Date:	1	40.00	40.00
23	70km/h sticker	W	1	25.00	Ma 25.00 1552
24	Rear windscreen sealant		1	60.00	Ma 60.00 4052
				_	125.00
	LABOUR				10.1
	To remove and refix rear w		1	150.00	150.00
26	To remove and refix rear be	umper sensor	1	100.00	100.00 501
27	To transfer damaged tailga	te interior mechanism to new tailgate	1	120.00	120.00 601
					0-(



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : THAI SING FOODSTUFFS INDUSTRY PTE LTD

42 WOODLANDS TERRACE, S

SINGAPORE 738457

TEL : 6755 2166

ATTN:

YOUR REF NO : XD2753S

CLAIM TYPE

: THIRD PARTY

TP INS. CO.

: ALLIED WORLD ASSURANCE COMPANY LTD

ACCIDENT DATE : 06/08/2020 TP VEH REG NO : XD2753S

FAX:

ESTIMATE

NO

: QUOT202008-000025(00)

DATE

: 14/08/2020

POLICY NO : 2100335538-07

VEH REG NO : GBC6022H

MAKE/MODEL : NISSAN URVAN 3.0 5MT ABS

AB 5DR LWB PANEL

CHASSIS NO : JN1MG4E25Z0796846

ENGINE NO

: ZD30297310K

REG. DATE

: 2013

Estimate Repair Cost to Vehicle No: GBC6022H

Description	Quantity	Unit Price	Amount
To check and rectify wiring system To panel beat and straighten rear chassis frame, rear floorboard panel, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same To putty and spray same on affected areas To supply and paste artwork on tailgate	1 1 1	800.00 800.00 800.00 800.00	\$\$ 201 1,000.00 600 1,000.00 600 800.00 180.00 1201 2,430.00
		TOTAL DD GST @ 7% GRAND TOTAL	\$\$ 7,266.28 508.64 \$\$ 7,774.92

SINGAPORE DOLLAR SEVEN THOUSAND SEVEN HUNDRED SEVENTY-FOUR AND CENTS NINETY-TWO ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

MLHM20066731 / Lai Huat (Meng Kee) Motor Pte Ltd - Sin Ming ENTRY DATE & TIME: 07/08/2020 14:12 SUBMITTED BY: [To Be Confirmed]

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report

07/08/2020 14:12

Date Of Accident

06/08/2020 16:00

Exact Location Of Accident

SEMBAWANG WAY

Country/State of Loss

SINGAPORE DETAILS OF OWN VEHICLE

Vehicle Registration Number

GBC6022H

sured/Policyholder

Name Of Registered Owner

THAI SING FOODSTUFFS INDUSTRY PTE LTD

Co Reg No

1XXXXX800G

Email Address

NOEMAIL

Mobile Phone No

Alternative Phone No

Office-67552166

Vehicle Particulars

Manufacturer

NISSAN

Model

URVAN-3.0 5MT ABS AB 5DR LWB PANEL (A)

Exact Purpose for which vehicle was being used at time of

COMPANY USE

Are you claiming under your own insurance policy for

repair to your vehicle?

THIRD PARTY

If No, Please state action to be taken Vehicle Category

COMMERCIAL VEHICLE

Insurance Company

ame of Insurance Company

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage

COMPREHENSIVE NO

Fleet Policy

2100335538-07

Policy Number

Cover Note Number

Driver

LU YUTING Name of Driver SXXXX552D NRIC No 12/12/1986 Date Of Birth OUTDOOR Occupation

Date Of Driving Pass

22/08/2017

Driving Experience

2 YEARS AND 11 MONTHS

Gender

2

R

LI

MALE

Mobile Number

(LOCAL) +65-86989473

Fax Number

Contact Number **EMail Address**

MARTINSHIMINLU911@GMAIL.COM BLK 269A YISHUN STREET 22 #07-527

Address Postcode

761269

ariver an employee of the Insured's Company No, Relationship of the Driver with the Insured YES Vehicle Registration Number of Driver's Own Vehicle Insurance Company of Driver's Own Vehicle General Information of the Accident Type Of Accident COLLISION - HEAD TO REAR Weather Conditions CLEAR Road Surface DRY Other Information Was any foreign vehicle involved in this accident? NO Number of vehicles (including own vehicle) involved in the Was any body injured in the Accident? NO Was any injured conveyed to hospital by ambulance? NO Was any other material or property damaged? YES I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO Number of Passengers (Including Driver) **Details of Police Action** Was the accident reported to the police? If Yes, Please state which Police Station Was notice of intended Prosecution given? NO If Yes, against whom? Circumstances of Accident REFER TO SKETCH PLAN. Attachment(s) Are accident photos available for attachment? YES Was there any video captured by Car Camera? NO Was there any audio recorded? NO DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number XD2753S Vehicle Make/Model/Colour **Details Of Properties** Vehicle Category COMMERCIAL VEHICLE Name of Driver LIM WEI CHONG NRIC/Passport Number SXXXX463J Contact Number Address Postcode Insurance Company Name Nature Of Damage

No. Of Passenger (Including Driver)