

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated: 27/08/2020 User ID : PohSuan

2	Section A - Accident Details
Registration Number	SHB1336U
Case Reference Number	TAX/08/20/2038
Registration Date	28/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	ONG SWEE CHYE
Type of Accident	Head to Rear
Accident Date and Time	14/8/2020 8:25 AM
Accident Reported Date and Time	14/8/2020 2:36 PM
s Surveyor Required?	Yes
Survey by	
/ehicle is Towed Back?	No
owed Back Date and Time	
Replacement Vehicle issued?	No
ob Card Number	24107838
pecial Instruction to ARC,if	REAR TAXI DAMAGE
repared Date and Time	14/8/2020 4:12 PM
hassis Number	
ileage	
ork Shop	
epair Completion Date and me	

	Section B - Summary of Re	epair Estimates
Summary of Repair Estimate	ates	
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$338.00	\$200.00
Total Spray Cost	\$738.00	\$200.00
Total Spare Part Cost	\$1,499.10	\$538.73
Total Other Cost	\$360.00	\$20.00
TOTAL COST	\$2,935.10	\$958.73 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Kim Ming Chin	Sun Pin (LKK) / ERGO
ARC / Surveyor Sign Off Date	14/08/2020 4:23 PM	17/08/2020 2:13 PM
Signature	1	2
Remarks		P/P, before paint photo



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore
FAX Number: 63685592

Estimator Telephone Number: 68662623

Accident Reporting Number: 68662672

									Date Generate User ID	ed : 27/08/2020 : PohSuan
			Section C - Quotation and A	ccident In	voice Details	5			· · · · · · · · · · · · · · · · · · ·	
Quota	tion Numb	er QN-2	008-0322	Invoice Nu	umber					
Quota	tion Date	27.08	.2020	Invoice Da	ite					
Invoice	e Amount			Prepared [Date					
			Section D	- Details o	of Repair Est	imates				
	- Labour W	orks								
Job Sc	et satua			Quota	ition from AF	₹		Adjusted	by Surveyor	16
TO REPAIR REAR PORTION			\$338.00				applicab \$200.00	le		
Total Labour			\$338.0	\$338.00						
Dart 2	Corou Dal							\$200.00		
		nting & Pan	el Beating Related Works							
Job Sc				Quota	ition from AF	RC		Adjusted	by Surveyor,	if
		AR BUMPER		\$378.0	\$378.00				e	
			REINFORCEMENT	\$180.0	00			\$0.00		_/_
		ER RR BUI		\$180.0	00			\$0.00		
Total Sp	oray Paintii	ng & Panel	Beating	\$738.0	00			\$200.00		_
Part 3	Other Con	e - Annide	at and Assistant S					7230.00		
		.s - Accider	it and Accident Repair Rela	ed Expens	se					
Job Sco				Quotat	ion from AR	С		Adjusted I	by Surveyor,	if
TO TEST AND REFIX REVERSE SENSOR SYSTEM			\$120.00	\$120.00				<u></u>		
			EM FUNCTION	\$80.00				\$20.00		/
O REPI	LACE SUNI	DRY PARTS		\$100.00)			\$0.00		/
O WASH AND VACUUM			\$60.00							
otal Other Costs				\$360.00		· · · · · · · · · · · · · · · · · · ·		\$20.00		
ort 4 C	Sansa B							\$20.00	· · · · · · · · · · · · · · · · · · ·	
art		/ Material (]
umber	Portion	Stock Number	Part Name	Quantity	y List Price (\$)	Discount (%)	Final Price		Surveyor	-
		13	9 COVER, RR BUMPER ASSY	1.00	\$423.90	100.00	\$0.00	Approved Replace	Approved Repair	
		5246247 30	0 PAD, RR BUMPER, RH & LH , 1	0.00	\$3.80	0.00	\$0.00	Replace	Not Given X	4
			PAD, RR BUMPER, RH &	0.00	\$3.80	0.00	\$0.00	Replace	Not Given X	
			PAD, RR BUMPER, RH &	0.00	\$3.80	0.00	\$0.00	Replace	Not Given	
		52191470	LH, 3 D SEAL, RR BUMPER ARM,	0.00	\$11.00	0.00	\$0.00	Replace	Not Given	
		30 52576470	RH & LH RETAINER, RR BUMPER,	0.00	\$111.50	0.00	\$0.00	Replace	/	
*****		52453470	LH GUARD, RR BUMPER,	1.00	\$558.30	25.00	\$418.73		Not Given	/ 35° ·
	-	10	LOWER PAD, RR BUMPER, CTR	0.00	\$2.20			Replace	Replace X	1 0000
		10	FILLER, RR BUMPER, LH			0.00	\$0.00	Replace	Not Given Y	
		00	SENSOR REVERSE		\$119.90	0.00	\$0.00	Replace	Not Given 🗡	
		52002470		0.00	\$180.00	0.00	\$0.00	Replace	Not Given X	and the state of t
		30	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Not Given X	OCO.
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	958. p/p 2dm
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	0.00	\$1.50	0.00	\$0.00	Replace	Not Given X	O/P
tal					\$1,798.50		\$538.73			1
ded Spa	are Parts / I	Vaterial Lie	age After Surveyor Signed o			L				226
	Portion	Stock	Part Name							
mber	. 0.0011	Number	rait ivallie	Quantity	List Price \$	Discount (%)			Surveyor Check	
al		1						-HOAV	ZIIECK	