

Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Steve (LKK)

Email: ryderautoworkshop@gmail.com
Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : SKQ633D

WHL AML
18/8/19, 11.00am

Model:

MAZDA 6
(30/10/2014)

Accident Date : 13/8/2020

Location : BUKIT TIMAH LINK

L/S 3 days
Ry AL sm

3P:

SKR8846Z (AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper / DD	-	-	881.40
2	10pcs	Rear bumper clips / MC	-	80.00	391
3	2 pcs	Rear bumper tow cover / P15	-	-	120.00
4	1pc	Rear enforcement / DD	-	652.20	473
5	2 Apcs	Rear reverse sensor / Shrd	-	350.00	200
Sub-Total:			0.00	1082.20	1001.40
			20%	0%	10%
After Less %:			0.00	1082.20	901.26
Labour					
1		To remove and replace rear damage parts		800.00	300
2		To spray painting.		800.00	400
3		To remove & replace rear tail-gate.		100.00	X
4		To remove and replace rear reverse sensor		40.00	30
5		To check wiring.		50.00	30
Sub-Total:				1,790.00	760
Total:				3,773.46	
After Less 20%:				3,018.77	

List
Nett
45 List
Nett


Chan

List - 1491.40
- 20%
1,121.12
Nett - 230

Chan San Choon

Director

DipEng, AAE MIMI, MSAE(Aust)



8778 1999
24 hr accident call



- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SKQ633D ESTIMATE PRICE AND PARTS TO BE CONFIRMPg1

1121.12
230
760
211.12

L/S - 1688-89
= 1790