

Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Steve (LKK)

Email: ryderautoworkshop@gmail.com
Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : SKQ633D

Accident Date : 13/8/2020

Location : BUKIT TIMAH LINK

W/L P/L
18/8/20, 11.00am

L/S 3 days
Ry AL sm

Model:

MAZDA 6
(30/10/2014)


3P:

SKR8846Z (AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper / DD	-	-	881.40
2	10pcs	Rear bumper clips / MC	-	80.00	-
3	2 pcs	Rear bumper tow cover / MS	-	-	120.00
4	1pc	Rear enforcement / DD	-	652.20	-
5	2 Apcs	Rear reverse sensor / Shaded	-	350.00	-
Sub-Total:			0.00	1082.20	1001.40
			20%	0%	10%
After Less %:			0.00	1082.20	901.26
Labour					
1		To remove and replace rear damage parts	800.00	300	
2		To spray painting.	800.00	400	
3		To remove & replace rear tail-gate.	100.00	X	
4		To remove and replace rear reverse sensor	40.00	30	
5		To check wiring.	50.00	30	
Sub-Total:				1,790.00	
Total:				3,773.46	
After Less 20%:				3,018.77	

Chan San Choon

Director
DipEng, AAE MIMI,MSAE(Aust)



8778 1999
24 hr accident call



- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SKQ633D ESTIMATE PRICE AND PARTS TO BE CONFIRMPg1