

ASSIGNMENT

COB Nov 2024

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. MSD/VMS/20-506747-WTClaims No. MSC/V/20-000658

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR. Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SH 7864K Yr Regn: Nov 2016Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.o. 1798Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 675142 T/Radio: Insured / Std / NI / NAEng/No: 2ZRR963184C/No: JTDKB3Fu903537558Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front _____ Rear _____

R/Bal. S mm R/Bal. S mmL/Bal. S mm L/Bal. S mmD.O.A. 10/08/2020 D.O.I. 17/08/2020Survey held at: Bijest Sin Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Portion

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MSG PY 2001G

Check consistency of damage.

21/08/20 @ 9.5m revised to Jowin Tay via Meimen.

17/10/2020 Jowin 2/3 12500/- with 8 days 2 re (Red 624526.59, 662.)

Date/Time, File Pass to?



Prel. Report

1) 18/11/2024



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 8Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Report Format:

MCD-TP

Lump Sum / I.B.I. (\$)

12500

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 15-Aug-20

INSURANCE: MSIG

MODEL: TOYOTA PRIUS

VEHICLE NO.: SH7864K

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR DOOR RUBBR SEAL OUTER <i>tan</i>	1	\$257.90	\$257.90
PANEL SUB-ASSY, REAR DOOR, RH <i>tan / Dented</i>	1	\$1,258.30	\$1,258.30
REAR DOOR HINGE UPPER <i>HH</i>	1	\$82.30	\$82.30
REAR DOOR HINGE LOWER <i>HH</i>	1	\$82.30	\$82.30
REAR DOOR CHECK <i>HH</i>	1	\$153.00	\$153.00
REAR DOOR TRIMBOARD <i>HH</i>	1	\$725.00	\$725.00
MOTOR, POWER WINDOW REGULATOR FRT, RH <i>HH</i>	1	\$941.80	\$941.80
REGULATOR, FRONT DOOR WINDOW REAR, RH <i>HH</i>	1	\$228.40	\$228.40
REAR DOOR OUTER HANDLE <i>brn</i>	1	\$93.00	\$93.00
REAR DOOR OUTER MOULDING <i>SH</i>	1	\$128.60	\$128.60
REAR DOOR RUBBER SEAL OUTER <i>replaced</i>	1	\$257.90	\$257.90
GLASS, SUB-ASSY, REAR DOOR, RH <i>shattered</i>	1	\$780.50	\$780.50
MOULDING, FRONT DOOR WINDOW FRAME, REAR RH <i>HH</i>	1	\$53.70	\$53.70
LOCK ASSY, BACK DOOR <i>HH</i>	1	\$444.10	\$444.10
Door Centre Pillar Outer (RH) <i>HH Dented</i>	1	\$1,590.60	\$1,590.60
PANEL SUB-ASSY, FRONT DOOR, RH <i>Dented / torn</i>	1	\$1,264.00	\$1,264.00
FRONT DOOR INNER LOCK <i>HH</i>	1	\$688.80	\$688.80
FRONT DOOR HINGE UPPER <i>HH</i>	1	\$82.30	\$82.30
FRONT DOOR HINGE LOWER <i>HH</i>	1	\$91.20	\$91.20
FRONT DOOR CHECK <i>HH</i>	1	\$153.52	\$153.52
FRONT DOOR TRIMBOARD <i>HH</i>	1	\$725.00	\$725.00
FRONT DOOR KEY LOCK SET <i>HH</i>	1	\$428.90	\$428.90
FRONT DOOR RUBBER SEAL <i>HH</i>	1	\$257.00	\$257.00
FRONT DOOR COMFORT LOGO <i>Hee</i>	1	<i>SH</i> \$75.00	\$75.00
Rocker Panel Outer Garnish <i>SH</i>	1	\$576.00	\$576.00
Rocker Panel Outer <i>repr</i>	1	\$519.80	\$519.80
Rocker Panel Enforcement (RH) <i>HH</i>	1	\$ 974.30	\$974.30
FRONT BUMPER COVER <i>tan</i>	1	\$499.90	\$499.90
FRONT BUMPER REINFORCEMENT <i>HH</i>	1	\$696.40	\$696.40
FRONT BUMPER REINFORCEMENT ABSORBER <i>HH</i>	1	\$115.70	\$115.70
FRONT BUMPER LOWER REINFORCEMENT <i>HH</i>	1	\$364.20	\$364.20
FRONT BUMPER LOWER REINFORCEMENT BRACKET <i>HH</i>	1	\$330.00	\$330.00
FRONT BUMPER SPONGE <i>HH</i>	1	\$78.80	\$78.80
FRONT BUMPER LOWER GRILLE <i>HH</i>	1	\$148.60	\$148.60
LAMP ASSY, FOG, RH <i>monity broken</i>	1	\$920.00	\$920.00
FRONT BUMPER CLIPS <i>Hee</i>	1	\$22.00	\$22.00
FRONT BUMPER SIDE RETAINER <i>SH</i>	1	\$77.00	\$77.00
FRONT LOWER CROSSMEMBER <i>HH</i>	1	\$357.70	\$357.70
FRONT UNDER COVER <i>HH</i>	1	\$180.80	\$180.80
FRONT BUMPER TOP GARNISH <i>HH</i>	1	\$225.40	\$225.40
COVER, FRONT BUMPER HOLE, RH <i>dislodged</i>	1	\$28.38	\$28.38

SH

ABSORBER, FRONT BUMPER, LOWER <i>NH</i>	1	\$127.70	\$127.70	X
UNIT ASSY, HEADLAMP, RH (LED) <i>mounting broken</i>	1	\$3,455.00	\$3,455.00	✓
HEADLAMP ECU <i>NH</i>	1	\$682.60	\$682.60	X
HEAD LAMP PANEL (RH) <i>NH</i>	1	\$240.10	\$240.10	X
TOP PANEL SIDE <i>NH</i>	1	\$145.90	\$145.90	X
RADIATOR ASSY <i>NH</i>	1	\$1,841.80	\$1,841.80	X
COOLANT <i>NH</i>	1	\$45.00	\$45.00	X
DEFLECTOR, RADIATOR SIDE, RH <i>NH</i>	1	\$83.50	\$83.50	X
CONDENSER ASSY, W/RECEIVER <i>NH</i>	1	\$1,336.60	\$1,336.60	X
FENDER SUB-ASSY, FRONT RH <i>Dent</i>	1	\$945.30	\$945.30	✓
FRONT FENDER SHIELD <i>deformed from</i>	1	\$198.50	\$198.50	✓
FRONT FENDER SHIELD CLIP <i>Nec</i>	1	\$14.90	\$14.90	✓
FRONT FENDER HYBRID EMBLEM, RH <i>Nec</i> 53.50	1	\$86.50	\$86.50	✓
BRACKET, FRONT SIDE PANEL, RH <i>NH</i>	1	\$86.30	\$86.30	X
FRONT WHEEL RIM <i>fit cut</i>	1	\$1,570.55	\$1,570.55	✓
FRONT WHEEL HUB CAP <i>HF</i>	1	\$175.80	\$175.80	X
FRONT WHEEL HUB BEARING <i>2 Dent</i>	1	\$559.94	\$559.94	✓
FRONT SUSPENSION LOWER ARM (RH) <i>2 distorts</i>	1	\$631.90	\$631.90	✓
FRONT SHOCK ABSORBER (RH) <i>2 distorts</i>	1	\$398.20	\$398.20	✓
ABSORBER TOP MOUNTING <i>NH</i>	1	\$196.20	\$196.20	X
FRONT DRIVE SHAFT (RH) <i>NH</i>	1	\$1,764.00	\$1,764.00	X
RACK & PINION ASSY <i>NH</i>	1	\$1,621.30	\$1,621.30	X
BAR, STABILIZER <i>NH</i>	1	\$352.40	\$352.40	X
KNUCKLE, STEERING, RH <i>2 distorts</i>	1	\$580.80	\$580.80	✓
JOINT ASSY, LOWER BALL, FRONT (RH) <i>NH</i>	1	\$199.98	\$199.98	X
DISC, FRONT <i>NH</i>	1	\$420.67	\$420.67	X
END SUB-ASSY, TIE ROD, RH <i>NH</i>	1	\$159.30	\$159.30	X
SENSOR, SPEED, FRONT RH <i>NH</i>	1	\$446.50	\$446.50	X
FRONT BRAKE CALIPERS <i>NH</i>	1	\$882.90	\$882.90	X
SUB TOTAL	15827.77		\$36,208.24	
LESS 20% <i>55%</i>			\$7,241.65	
DISCOUNTED TOTAL	11870.82		\$28,966.59	
REAR DOOR ADVERTISEMENT LOGO <i>Nec</i> SN	1	\$100.00	\$100.00	✓
FRONT TYRE (RH) <i>NH</i> SN	1	\$216.00	\$216.00	X
SUB TOTAL	175.00		\$316.00	
Labour Charge				
Panel Beating	1	\$1,600.00	\$1,600.00	1000/-
Spray Painting Charge	1	\$1,400.00	\$1,400.00	1000/-
Wiring Charge	1	\$160.00	\$160.00	30/-
Tuff Kote	1	\$160.00	\$160.00	40/-
Towing Charge	1	\$80.00	\$80.00	NH
Transfer of Door Mechanism FRONT	1	\$80.00	\$80.00	60/-
Re-set Frt Power Window System	1	\$200.00	\$200.00	NH
Transfer of Door Mechanism REAR	1	\$80.00	\$80.00	60/-
Re-set Rear Power Window System	1	\$200.00	\$200.00	NH
Four Wheel Alignment	1	\$120.00	\$120.00	60/-
Remove/Refix Undercarriage (Frt)	1	\$400.00	\$400.00	120/-

Re-set Frt ABS System	1	\$200.00	\$200.00	NH
Remove/Refix Radiator	1	\$90.00	\$90.00	NH
Remove/Refix Aircon & Refill Gas	1	\$130.00	\$130.00	NH
Front Chassis Alignment Charge	1	\$220.00	\$220.00	NH
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	1801-
2580.00				
TOTAL LABOUR			\$5,670.00	
ESTIMATE TOTAL			\$34,952.59	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

17/08/2020 @ 1715hr

Not Authorised

L/Sure 8 days.

1 year

LKK Auto

8

Check consistency
of damage.

14625.82

supp 1010.40

15636.22

L/S 12500/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

33026.59

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 21-Aug-20

INSURANCE: MSIG

MODEL: TOYOTA PRIUS

VEHICLE NO.: SH7864K (S)

DESCRIPTION	QTY	LIST PRICE	AMOUNT
ROOF TOP SIDE PANEL (RH) <i>repa</i>	1	\$408.60	\$408.60
TAIL LAMP ASSY (UPPER) RH <i>Scratched</i>	1	\$557.90	\$557.90
REAR FENDER, RH <i>repa</i>	1	\$836.70	\$836.70
REAR FENDER TOP COVER (BLACK COLOR)(RH) <i>Scratched</i>	1	\$301.10	\$301.10
RR WINDOW ASSY, QUARTER, (RH) <i>Scratched</i>	1	\$488.20	\$488.20
SUB TOTAL			\$2,592.50
LESS <i>20% 25%</i>			\$518.50
DISCOUNTED TOTAL			\$2,074.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Ryan

2kk Auto

[Signature]

1347.20

25% 1010.40

Phone Number:

Fax Number:

Customer:		Date:	18/8/2020 11:03 AM
Company:		VIN	
License NO:	SH7864K	Technician:	
Odometer:		Order NO:	

VEHICLE ALIGNMENT REPORT

TOYOTA, PRIUS CDGE ZVW50R-AHXEBW, 18-18 (Customized)

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	6°54'	6°35'	8°05'	7°19'
		Right	6°40'	6°35'	8°05'	1°05' *
	Camber	Left	-0°16'	-0°55'	0°35'	-0°11'
		Right	-0°23'	-0°55'	0°35'	-0°58' *
	Toe	Left	0°02'	-0°03'	0°08'	0°31' *
		Right	-0°22' *	-0°03'	0°08'	1°04' *
Total		-0°20' *	-0°06'	0°17'	1°35' *	
Rear	Camber	Left	-1°28'	-2°00'	-0°30'	-1°19'
		Right	-1°38'	-2°00'	-0°30'	-1°52'
	Toe	Left	0°10'	0°02'	0°14'	0°10'
		Right	0°00' *	0°02'	0°14'	0°58' *
		Total	0°10'	0°05'	0°27'	1°08' *
	Thrust Angle		-0°05'	0°15'		0°24' *
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI		Left	13°43'	----	----	13°43'
		Right	13°43'	----	----	13°43'
Included Angle		Left	13°27' *	99°59'	99°59'	13°32' *
		Right	13°19' *	99°59'	99°59'	12°44' *
Toe Out On Turns		Left	----	99°59'	99°59'	----
		Right	----	99°59'	99°59'	----
Max Turn Inside		Left	----	99°59'	99°59'	----
		Right	----	99°59'	99°59'	----
Toe Curve Change		Left	----	0°00'	199°59'	----
		Right	----	0°00'	199°59'	----
Setback		Front	0.14" *	99.99"	99.99"	0.14" *
		Rear	-0.12" *	99.99"	99.99"	-0.12" *
Track Width Diff.			0.12"			0.12"
Wheel Base Diff.			0.26"			0.26"
Front Ride Height		Left	----	99.99"	99.99"	----
		Right	----	99.99"	99.99"	----
Rear Ride Height		Left	----	99.99"	99.99"	----
		Right	----	99.99"	99.99"	----
Frame Angle						----