

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref: CC4/ASM20008558/Bba3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:PETER			Date: 10-12-2020 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 149P	Veh. Inspected	SMA 4968Y
	Policy No.	VFX/P2348706	Coverage (\$)	0.00
	Claim No.	S0M02S90	Excess (\$)	0.00
	Assign From		Assign Date	17/08/2020
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HARRIER M GRADE	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JTEZB3GH30J002149	Colour	WHITE
	Odometer	43334	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/55 R18	BRIDGESTONE	5 mm
	L/H Front Tyre	235/55 R18	BRIDGESTONE	5 mm
	R/H Rear Tyre	235/55 R18	BRIDGESTONE	5 mm
	L/H Rear Tyre	235/55 R18	BRIDGESTONE	5 mm
4.	Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	14/08/2020	Inspection Date	17/08/2020
	Survey held at	TEAM AUTOPRO PTE LTD		
		160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days			