


Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
 Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: MITSUBISHI LANCER EX
 Engine/Chassis No.: CY4ASTXHR4B11F1CJA
 Date of accident:
 Damaged area: N/S Front

Date: 25/08/2020
 Claim Type: TP
 VRN: SJW8078J



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Bonnet	1	\$ 1,089.00	\$ 1,089.00
2	Bonnet lock	1	\$ 233.00	\$ 233.00
3	Bonnet Hinges	2	\$ 84.00	\$ 168.00
4	Front bumper	1	\$ 939.00	\$ 939.00
5	Front bumper bracket	2	\$ 75.00	\$ 150.00
6	Front bumper side retainer	2	\$ 68.00	\$ 136.00
7	Front bumper top grille	1	\$ 434.00	\$ 434.00
8	Front bumper top grille "MITSUBISHI" logo	1	\$ 66.00	\$ 66.00
9	Front bumper lower grille	1	\$ 346.00	\$ 346.00
10	Front bumper reinforcement	1	\$ 528.00	\$ 528.00
11	Front bumper impact absorber	1	\$ 169.00	\$ 169.00
12	Front support panel	1	\$ 478.00	\$ 478.00
13	Front support panel top garnish	1	\$ 206.00	\$ 206.00
14	Front fender n/s	1	\$ 623.00	\$ 623.00
15	Front fender cowling n/s	1	\$ 188.00	\$ 188.00
16	Headlamp n/s	1	\$ 1,150.00	\$ 1,150.00
17	Headlamp lower bracket n/s	1	\$ 68.00	\$ 68.00
18	Front foglamp n/s	1	\$ 286.00	\$ 286.00
19	Front foglamp garnish n/s	1	\$ 128.00	\$ 128.00
20	Front bumper lower cowling	1	\$ 167.00	\$ 167.00
			Subtotal	\$ 7,552.00
			List discount	10.00%
			Total	\$ 6,796.80

Repair Estimate

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front bumper clips	12	\$ 4.50	\$ 54.00
2	Front bumper lower cowling clips	6	\$ 4.50	\$ 27.00
3	Front bumper top grille clips	6	\$ 4.50	\$ 27.00
4	Front support panel top garnish clips	6	\$ 4.50	\$ 27.00
5	Front fender cowling n/s clips	8	\$ 4.50	\$ 36.00
6	Front licence plate	1	\$ 55.00	\$ 55.00
Total				\$ 226.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	5	\$ 1,000.00
2	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check functions including focusing headlamps.	0.25	\$ 50.00
3	Supply spray paint material and necessary items to respray front bumper, bonnet, support panel, n/s front fender and other affected area / panel.	5	\$ 1,000.00
4	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 2,150.00

Estimate Grand Total	\$ 9,172.80
-----------------------------	--------------------