

KV

Repair Estimate

Not Withheld

L/Smp @ 2450/h

Returning After Paint

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com


4 days

Make/Model: MITSUBISHI LANCER EX
 Engine/Chassis No.: CY4ASTXHR4B11F1CJA
 Date of accident:
 Damaged area: N/S Front

Date: 25/08/2020

Claim Type: TP

VRN: SJW8078J



List items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Bonnet R	1	\$ 1,089.00	\$ 1,089.00	X
2	Bonnet lock R	1	\$ 233.00	\$ 233.00	X
3	Bonnet Hinges R	2	\$ 84.00	\$ 168.00	X
4	Front bumper 891 n/s cm	1	\$ 939.00	\$ 939.00	✓
5	Front bumper bracket R	2	\$ 75.00	\$ 150.00	X
6	Front bumper side retainer n/s cm	2	\$ 68.00	\$ 136.00	✓
7	Front bumper top grille Sn	1	\$ 434.00	\$ 434.00	X
8	Front bumper top grille "MITSUBISHI" logo Sn	1	\$ 66.00	\$ 66.00	X
9	Front bumper lower grille Sn	1	\$ 346.00	\$ 346.00	X
10	Front bumper reinforcement R	1	\$ 528.00	\$ 528.00	X
11	Front bumper impact absorber Sn	1	\$ 169.00	\$ 169.00	X
12	Front support panel R	1	\$ 478.00	\$ 478.00	X
13	Front support panel top garnish Sn	1	\$ 206.00	\$ 206.00	X
14	Front fender n/s 574 Buz	1	\$ 623.00	\$ 623.00	✓
15	Front fender cowling n/s 141 cm	1	\$ 188.00	\$ 188.00	✓
16	Headlamp n/s 578 Cvt	1	\$ 1,150.00	\$ 1,150.00	✓
17	Headlamp lower bracket n/s Sn	1	\$ 68.00	\$ 68.00	X
18	Front foglamp n/s Sn	1	\$ 286.00	\$ 286.00	X
19	Front foglamp garnish n/s 116 Cvt/Rel	1	\$ 128.00	\$ 128.00	✓
20	Front bumper lower cowling Sn	1	\$ 167.00	\$ 167.00	X
Subtotal				\$ 7,552.00	
List discount				10.00%	
Total				\$ 6,796.80	

Repair Estimate

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front bumper clips <i>na</i>	12	\$ 4.50	\$ 54.00 ✓
2	Front bumper lower cowling clips <i>na</i>	6	\$ 4.50	\$ 27.00 X
3	Front bumper top grille clips <i>na</i>	6	\$ 4.50	\$ 27.00 X
4	Front support panel top garnish clips <i>na</i>	6	\$ 4.50	\$ 27.00 X
5	Front fender cowling n/s clips <i>na</i>	8	\$ 4.50	\$ 36.00 ✓
6	Front licence plate <i>na</i>	1	\$ 55.00	\$ 55.00 X
Total				\$ 226.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	5	\$ 1,000.00 400
2	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check functions including focusing headlamps.	0.25	\$ 50.00 20
3	Supply spray paint material and necessary items to respray front bumper, bonnet, support panel, n/s front fender and other affected area / panel.	5	\$ 1,000.00 400
4	To rust proof all affected portions after repair.	0.5	\$ 100.00 30
Total labour			\$ 2,150.00

Estimate Grand Total	\$ 9,172.80
----------------------	-------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date