



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2105333

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 29/07/2021
Reference CC4/FCI20008569/R1ea3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMT 1045E
Insured Veh. SHD 3906B
Claim No. D20003200MFSH
Policy No. D-20094922MFSH
Accident Date 12/08/2020
Inspection Date 18/08/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20008569/R1ea3q2	
			Date: 29/07/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 3906B	Veh. Inspected	SMT 1045E
	Policy No.	D-20094922MFSH	Coverage (\$)	0.00
	Claim No.	D20003200MFSH	Excess (\$)	0.00
	Assign From	VIC	Assign Date	17/08/2020
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA SIENTA HYBRID 1.5X	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	NHP1707167326	Colour	BLUE
	Odometer	12285 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm
	L/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm
	R/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm
	L/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	12/08/2020	Inspection Date	18/08/2020
	Survey held at	XINYA AUTO SERVICES PTE LTD BLK 1002 BUKIT MERAH LANE 3 #01-75 SINGAPORE 159719		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMT 1045E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAIL GATE	BENT	1,131.90	1,131.90
1	TAIL GATE WEATHERSTRIPE	NECESSARY	372.10	372.10
1	TAIL GATE LOCK	NOT NECESSARY	467.60	-
1	TAIL GATE NOS PLATE GARNISH	NOT NECESSARY	207.90	-
1	TAIL GATE STRICKER	NOT NECESSARY	39.80	-
1	REAR BUMPER CENTRE TOP	DEFORMED	848.10	848.10
1	REAR BUMPER CENTRE LOWER	CRACKED	198.20	198.20
1	REAR BUMPER RH	NOT NECESSARY	129.80	-
1	REAR BUMPER LH	DEFORMED	129.80	129.80
1	REAR BUMPER REVERSE SENSOR	NOT WORKING	397.81	397.81
2	REAR BUMPER REFLECTOR	N/S CRACKED / O/S NOT NECESSARY	119.62	59.81
2	REAR BUMPER RETAINER	NOT NECESSARY	151.60	-
1	REAR BUMPER BRACKET	NECESSARY	69.20	69.20
1	END PANEL OUTER	TO REPAIR SEE LABOUR	433.60	-
1	END PANEL GARNISH	NOT NECESSARY	207.80	-
1	END PANEL INNER	NOT NECESSARY	698.30	-
	LESS 25% DISCOUNT		-1,400.78	-801.73
			4,202.35	2,405.19
<u>SPECIAL NETT ITEMS</u>				
1	WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
6	WINDSCREEN CLIPS (SN)	NECESSARY	24.00	24.00
			84.00	64.00
<u>LABOUR</u>				
	TO REMOVE & REPLACE REAR BUMPERS ,TAILGATE ,AND PANEL BEAT CUT & WELD END PANEL OUTER .INCLUSIVE OF THE REPAIR OF END PANEL OUTER .		1,400.00	600.00
	TO PUTTY & SPRAY PAINT REAR BUMPER ,TAIL GATE AND OTHER AFFECTED AREA.		1,200.00	600.00
	TO CHECK & RECTIFY WIRING AND REPLACE REVERSE SENSOR .		120.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TUFF KOTE.		250.00	40.00
	TO REMOVE AND REFIT WINDSCREEN .		120.00	120.00
	PRIVATE HIRE SEAL AND INSPECTION .	NOT NECESSARY	20.00	-
	REAR WINDSCREEN 3M SOLAR FILM .	NOT NECESSARY	400.00	-
			3,510.00	1,420.00
GRAND TOTAL			7,796.35	3,889.19
RECOMMENDED COST OF REPAIRS				3,889.19

Report Ref No. CC4/FCI20008569/R1ea3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMT 1045E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMT 1045E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

