

XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719
E-mail : xinyaauto@singnet.com.sg
Tel: 6270 3481 Fax: 6278 7522

Date : 13/08/2020

Address : F.K.T TRANSPORT
10 TOH YI DRIVE
#02-351 TOH YI GARDENS
SINGAPORE 590010

Reference : TP 1251/08/20
Vehicle No : SMT 1045E
Make/Model : TOYOTA SIENTA
Insurance Co. : LIBERTY

RE : QUOTATION TO SMT 1045E FOR THIRD PARTY CLAIMS.

<u>PARTS REQUIRED</u>		<u>QTY</u>	<u>AMT \$</u>
1)	TAIL GATE <i>h</i> ✓	1	\$ 1,131.90
2)	TAIL GATE WEATHERSTRIPE <i>re</i> ✓	1	\$ 372.10
3)	TAIL GATE LOCK <i>X</i> NN	1	\$ 467.60
4)	TAIL GATE NOS PLATE GARNISH <i>X</i> NN	1	\$ 207.90
5)	TAIL GATE STRICKER <i>X</i> NN	1	\$ 39.80
6)	REAR BUMPER CENTRE TOP <i>de</i> ✓	1	\$ 848.10
7)	REAR BUMPER CENTRE LOWER <i>con</i> ✓	1	\$ 198.20
8)	REAR BUMPER RH <i>X</i> NN	1	\$ 129.80
9)	REAR BUMPER LH <i>de</i> ✓	1	\$ 129.80
10)	REAR BUMPER REVERSE SENSOR <i>re</i> ✓	1	\$ 397.81
11)	REAR BUMPER REFLECTOR <i>con</i> ✓ LH	<i>1pc</i> 2 RH-NN	\$ 119.62
12)	REAR BUMPER RETAINER <i>re</i> ✓ <i>X</i> NN	<i>1pc</i> 2	\$ 151.60
13)	REAR BUMPER BRACKET <i>re</i> ✓	1	\$ 69.20
14)	END PANEL OUTER <i>repair</i> ✓	1	\$ 433.60
15)	END PANEL GARNISH <i>X</i> NN	1	\$ 207.80
16)	END PANEL INNER <i>X</i> NN	1	\$ 698.30
LIST PRICE TOTAL			\$ 5,603.13
LESS DISCOUNT 25%			\$ 1,400.78
LIST PRICE TOTAL AFTER LESS			\$ 4,202.35
17)	WINDSCREEN SEALANT <i>re</i> ✓	1	\$ 60.00 <i>40</i>
18)	WINDSCREEN CLIPS <i>re</i> ✓	6	\$ 24.00
NETT PRICE TOTAL			\$84.00
TOTAL PARTS COST			\$4,286.35

LABOUR AND MISCELLANEOUS CHARGES

- | | | |
|----|---|-------------------------------|
| 1) | TO REMOVE & REPLACE REAR BUMPERS, TAILGATE, AND PANEL BEAT CUT & WELD END PANEL OUTER | \$ 1,400.00 600
(7 DAYS) |
| 2) | TO PUTTY & SPRAY PAINT REAR BUMPER, TAIL GATE AND OTHER AFFECTED AREA. | \$ 1,200.00 600
(6 PANELS) |
| 3) | TO CHECK & RECTIFY WIRING AND REPLACE REVERSE SENSOR. | \$ 120.00 60 |
| 4) | TUFF KOTE | \$ 250.00 40 |
| 5) | TO REMOVE AND REFIT WINDSCREEN. | \$ 120.00 |
| 7) | PRIVATE HIRE SEAL AND INSPECTION. ? ? | \$ 20.00 X |
| 8) | REAR WINDSCREEN 3M SOLAR FILM ? | \$ 400.00 X |

LABOUR TOTAL

\$ 3,510.00

TOTAL ESTIMATED REPAIR COST

\$ 7,712.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue
Hp 90010068
5 days
P/P
18/08/2020 @ 1450
Resurvey before paint