

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 45561

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0573/2020/NS
Date : 17-Aug-20

Vehicle IN workshop. Please arrange for survey.

Your insured veh no : **SMN 6035 H**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Tapis Tknik Pte Ltd
Address : 18 Kaki Bukit Road 3
#01-08
Singapore 145978
Telephone : (Office) +65 67426996
Type of Claim : Third Party Claims
Policy No. : 2100349259-06
Vehicle No : **EU 702 M**
Model Code : Audi A4 1.8T FSI MU 8K203
Model / Year : 28/8/2013
Engine No : CJE 060974
Chassis No : WAUZZZ8K4EA017843
Mileage : 45135
Date In : 15-Aug-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-Aug-20
Place of Accident : Riverina Crescent S518290

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. EU 702 M

<u>S/n</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendations</u>
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00	✓ ✓
2	To dismantle and renew rear bumper and rear bumper lower spoiler. To inspect rhs tail lamp panel. Re-organise crash management components. Reinstall all parts removed.	\$ 1,050.00 500	✓
3	To respray rear bumper and rear lid. ✓ ✗	\$ 2,000.00 550	✓
4	To carry out diagnostic check. ✓	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: <u>\$ 3,522.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel 6366 2323 Fax 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EU 702 M

S/N	Parts Description	Damaged Parts & Prices		
			S/Nett	Remarks
1	REAR BUMPER <i>deh d</i>	\$	2,273.00 ✓	1,818.40
2	REAR BUMPER FIXING PARTS <i>not nec</i>	\$	225.00 ✗	
3	REAR BUMPER SPOILER <i>lit</i>	\$	264.00 ✓	210.80
4	REAR BUMPER CARRIER <i>? not nec</i>	\$	636.00 ✗	
5	REAR BUMPER SECURING STRIP <i>? not nec</i>	\$	14.00 ✗	
6	REAR BUMPER BRACKET HOLDER - RH <i>not nec</i>	\$	220.00 ✗	
7	REAR BUMPER GUIDE SECTION - RH UPPER } <i>nec</i>	\$	22.00 ✓	17.52
8	REAR BUMPER GUIDE SECTION - RH UPPER }	\$	45.00 ✓	35.36
9	REAR PARKING AID SENSOR <i>? not nec</i>	2	TBC ✗	
10	REAR BUMPER WIRING SET <i>? not nec</i>	\$	510.00 ✗	
11	LED TAIL LIGHT - RH <i>xt nec</i>	\$	1,063.00 ✗	
12	LED TAIL LIGHT - RH <i>incl d.</i>	\$	1,096.00 ✓	850.40
13	VENT TRIM <i>deformed</i>	\$	72.00 ✓	56.88
14	PACKING ADHESIVE	\$	18.00 ✗	
15	AUDI EMBLEM	\$	122.00 ✗	
16	A.8T INSCRIPTION	\$	95.00 ✗	
17	A4 INSCRIPTION	\$	95.00 ✗	
18	SUNDRIES <i>not nec</i>	\$	300.00 ✗	
TOTAL SPARE PARTS CHARGES		:	\$ 7,070.00	
TOTAL LABOUR CHARGES		:	\$ 3,522.00	
GRAND TOTAL		:	\$ 10,592.00	

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 18/08/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.	PA/TP/0573/2020/NS
Date	2-Sep-20
Service Advisor	Glory Tan
Pages	1 OF 1
Regn No	EU 702 M
Model No	Audi A4 1.8T FSI MU 8K203

Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	To repair rhs tail lamp panel and rhs rear inner connecting plate.	\$ 1,000.00	500
2	To respray rhs tail lamp panel and rhs rear inner connecting plate.	\$ 1,500.00	550
TOTAL		\$ 2,500.00	

For Premium Automobiles Pte Ltd

Adrian Ling
H.S. 22/09/20 _____
Authorized Signature

Add 2 days.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 45561

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0573/2020/NS
Date : 17-Aug-20

Vehicle IN workshop. Please arrange for survey.

Your insured veh no : SMN 6035 H

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian,

5 days - ok - Jy - 09 Oct 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Tapis Tknik Pte Ltd
Address : 18 Kaki Bukit Road 3
#01-08
Singapore 145978
Telephone : (Office) +65 67426996
Type of Claim : Third Party Claims
Policy No. : 2100349259-06
Vehicle No : **EU 702 M**
Model Code : Audi A4 1.8T FSI MU 8K203
Model / Year : 28/8/2013
Engine No : CJE 060974
Chassis No : WAUZZZ8K4EA017843
Mileage : 45135
Date In : 15-Aug-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-Aug-20
Place of Accident : Riverina Crescent S518290

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. EU 702 M

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$	280.00 \$	280.00
2	To dismantle and renew rear bumper and rear bumper lower spoiler. To inspect rhs tail lamp panel. Re-organise crash management components. Reinstall all parts removed.	\$	1,050.00 \$	500.00
3	To respray rear bumper and rear lid.	\$	2,000.00 \$	550.00
4	Supplementary	\$	2,500.00 \$	1,050.00
5	To carry out diagnostic check.	S/N \$	192.00 \$	192.00
TOTAL LABOUR CHARGES		:	\$ 6,022.00 \$	2,572.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EU 702 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER	\$ 2,273.00	\$ 1,818.40
2	REAR BUMPER FIXING PARTS	\$ 225.00	
3	REAR BUMPER SPOILER	\$ 264.00	\$ 210.80
4	REAR BUMPER CARRIER	\$ 636.00	
5	REAR BUMPER SECURING STRIP	\$ 14.00	
6	REAR BUMPER BRACKET HOLDER - RH	\$ 220.00	
7	REAR BUMPER GUIDE SECTION - RH UPPER	\$ 22.00	\$ 17.52
8	REAR BUMPER GUIDE SECTION - RH UPPER	\$ 45.00	\$ 35.36
9	REAR PARKING AID SENSOR	2	TBC
10	REAR BUMPER WIRING SET	\$ 510.00	
11	LED TAIL LIGHT - RH	\$ 1,063.00	
12	LED TAIL LIGHT - RH	\$ 1,096.00	\$ 850.40
13	VENT TRIM	\$ 72.00	\$ 56.88
14	PACKING ADHESIVE	\$ 18.00	
15	AUDI EMBLEM	\$ 122.00	
16	A.8T INSCRIPTION	\$ 95.00	
17	A4 INSCRIPTION	\$ 95.00	
18	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS CHARGES		\$ 7,070.00	\$ 2,989.36
TOTAL LABOUR CHARGES		\$ 6,022.00	\$ 2,572.00
GRAND TOTAL		\$ 13,092.00	\$ 5,561.36

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.
bl-02/10/20

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0573/2020/NS 2-Sep-20 Glory Tan 1 OF 1 EU 702 M Audi A4 1.8T FSI MU 8K203
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	To repair rhs tail lamp panel and rhs rear inner connecting plate.	\$ 1,000.00	\$ 500.00
2	To respray rhs tail lamp panel and rhs rear inner connecting plate.	\$ 1,500.00	\$ 550.00
TOTAL		\$ 2,500.00	\$ 1,050.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant