

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: [Nora.khai@premiumauto.com.sg](mailto:Nora.khai@premiumauto.com.sg) / [claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg)

**WIP : 45561**

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/0573/2020/NS  
**Date** : 17-Aug-20

**Vehicle IN workshop. Please arrange for survey.**

**Your insured veh no : SMN 6035 H**

### **AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Tapis Tknik Pte Ltd  
**Address** : 18 Kaki Bukit Road 3  
#01-08  
Singapore 145978  
**Telephone** : (Office) +65 67426996  
**Type of Claim** : Third Party Claims  
**Policy No.** : 2100349259-06  
**Vehicle No** : **EU 702 M**  
**Model Code** : Audi A4 1.8T FSI MU 8K203  
**Model / Year** : 28/8/2013  
**Engine No** : CJE 060974  
**Chassis No** : WAUZZZ8K4EA017843  
**Mileage** : 45135  
**Date In** : 15-Aug-20  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 15-Aug-20  
**Place of Accident** : Riverina Crescent S518290

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle. EU 702 M

<u>S/n</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendations</u>
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N	\$ 280.00	
2	To dismantle and renew rear bumper and rear bumper lower spoiler. To inspect rhs tail lamp panel. Re-organise crash management components. Reinstall all parts removed.		\$ 1,050.00	
3	To respray rear bumper and rear lid.		\$ 2,000.00	
4	To carry out diagnostic check.	S/N	\$ 192.00	
	<b>TOTAL LABOUR CHARGES</b>	<b>:</b>	<b><u>\$ 3,522.00</u></b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. EU 702 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER	\$ 2,273.00	
2	REAR BUMPER FIXING PARTS	\$ 225.00	
3	REAR BUMPER SPOILER	\$ 264.00	
4	REAR BUMPER CARRIER	\$ 636.00	
5	REAR BUMPER SECURING STRIP	\$ 14.00	
6	REAR BUMPER BRACKET HOLDER - RH	\$ 220.00	
7	REAR BUMPER GUIDE SECTION - RH UPPER	\$ 22.00	
8	REAR BUMPER GUIDE SECTION - RH UPPER	\$ 45.00	
9	REAR PARKING AID SENSOR	2	TBC
10	REAR BUMPER WIRING SET	\$ 510.00	
11	LED TAIL LIGHT - RH	\$ 1,063.00	
12	LED TAIL LIGHT - RH	\$ 1,096.00	
13	VENT TRIM	\$ 72.00	
14	PACKING ADHESIVE	\$ 18.00	
15	AUDI EMBLEM	\$ 122.00	
16	A.8T INSCRIPTION	\$ 95.00	
17	A4 INSCRIPTION	\$ 95.00	
18	SUNDRIES	\$ 300.00	
<b>TOTAL SPARE PARTS CHARGES</b>		<b>: \$ 7,070.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 3,522.00</b>	
<b>GRAND TOTAL</b>		<b>: \$ 10,592.00</b>	

All charges are not inclusive of GST.  
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** :  
**Surveyed Date** :  
**Authorised Date** :  
**Excess Cost** :  
**Liability** :  
**Remarks** :

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant