

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 17/08/2020

To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : GOO CHUON KWAN

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTPV01011802

Accident Date : 12/08/2020

Vehicle No : SLS-5009-B

Make & Model : MAZDA MAZDA5 WAGON 2.0 AT EU6 1998

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

1	REAR BUMPER <i>de cm</i>	951.40	✓
1	REAR BUMPER REINFORCEMENT <i>bf</i>	311.50	✓
2	REAR BUMPER RETAINER <i>? xsrc</i>	150.60	✗
2	REAR BUMPER BRACKET <i>? cm</i>	116.60	<i>58.30</i>
10	REAR BUMPER CLIPS <i>ree</i>	50.00	✓
2	REAR BUMPER REFLECTOR <i>xsrc</i>	170.80	✗
1	END PANEL <i>bf</i>	491.10	✓
1	END PANEL TOP GARNISH <i>de</i>	161.40	✓
1	TAILGATE ASSY <i>bf</i>	1,955.00	✓

Date : 17/08/2020

To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : GOO CHUON KWAN

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTPV01011802

Accident Date : 12/08/2020

Vehicle No : SLS-5009-B

Make & Model : MAZDA MAZDA5 WAGON 2.0 AT EU6 1998

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	TAILGATE GARNISH <i>de</i>	659.40	✓
1	TAILGATE TRIMBOARD <i>? for</i>	592.80	X
1	REAR LOGO <i>new</i>	86.10	✓
1	EMBLEM - MAZDA 5 <i>new</i>	121.70	✓
1	EMBLEM - SKYACTIV <i>new</i>	99.80	✓
1	TAILGATE LOCK <i>bt</i>	426.50	✓
1	TAILGATE WEATHERSTRIPE <i>new</i>	396.00	✓
1	REAR WINDSCREEN MOULDING <i>new</i>	87.60	✓
2	TAILGATE LAMP RH/LH <i>LH-? / RH-cm</i>	979.80	489.90 ✓
2	TAILLAMP RH/LH <i>RH-? / LH - old damage X SM</i>	1,346.00	X

Date : 17/08/2020

To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : GOO CHUON KWAN

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTPV01011802

Accident Date : 12/08/2020

Vehicle No : SLS-5009-B

Make & Model : MAZDA MAZDA5 WAGON 2.0 AT EU6 1998

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	SPARE TYRE PANEL RESTORE		X
	Sub Total	9154.10	
	Discount 20% On Parts	(1830.82)	
	Special Nett Item		
1	REAR NUMBER PLATE <i>hi</i> ✓	35.00 ✓	
1	REVERSE SENSOR <i>? nw</i> ✓	220.00 <i>? 200</i> ✓	
1	WINDSCREEN SEALANT <i>nw</i> ✓	50.00 ✓	
	Sub Total	305.00	
	Labour & Misc		
	LABOUR TO FACILITATE REPAIR	1,400.00 <i>800</i> ✓	

Date : 17/08/2020

To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : GOO CHUON KWAN

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTPV01011802

Accident Date : 12/08/2020

Vehicle No : SLS-5009-B

Make & Model : MAZDA MAZDA5 WAGON 2.0 AT EU6 1998

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO RESPRAY AFFECTED AREAS	1,400.00	800 900 ✓
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	120.00	✓
	TO REMOVE AND TRANSFER TAILGATE COMPONENTS	200.00	80 ✓
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	50.00	30 ✓
	RUST PROOFING	50.00	✓
	Sub Total	3220.00	
<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:		10,848.28	
		SUB TOTAL	
		GST 7.0 %	759.38
		TOTAL	11,607.66
			10,888.28#

Remarks:

7 days - P/P Resurvey b4 paint

Surveyor's name: RAUL - 4p 900,0068

Principal's name: GOO CHUON KWAN

Survey Date & Time: 17/08/2020 @ 1620